

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 02/10/2021

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 02/08/2021 1:15 PM		<b>4. Date/Time of Death</b> 02/08/2021 1:35 PM		<b>5. Fatal Case No</b> FAI-6490311-1	
<b>6. Mine Information</b>									
<b>a) Mining Company Name:</b>		Washington County Aggregates Inc.							
<b>b) Mine Name:</b>		Washington County Aggregates Inc							
<b>c) Parent of Mining Company:</b>		Kelley C Silvey							
<b>7. Mine Location Information</b>					<b>8. Mine ID Number</b>		<b>9. Union</b>		
<b>a) City</b> POTOSI		<b>b) County</b> Washington		<b>c) State</b> MO		23-02077		No	
<b>10. Primary Mineral Mined</b> Crushed & Broken Limestone Mining, N.E.C.				<b>11. Number of Employees</b>			<b>d) Mill/Prep Plant</b>		<b>e) Other</b>
				<b>a) Total</b> 12	<b>b) Underground</b>	<b>c) Open Pit/Quarry</b> 3	3		6
<b>12. Contractor Name</b>					<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>									
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>	
<b>16. Number of Contractor Employees</b>									
<b>a) Total</b>		<b>b) Underground</b>		<b>c) Open Pit/Quarry</b>		<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
<b>17. Number of Persons in Mine at Time of Accident</b>				<b>18. Number of Persons Unaccounted for</b>					
<b>a) Mine Employees</b> 6		<b>b) Contractor Employees</b>		<b>a) Mine Employees</b> 0		<b>b) Contractor Employees</b>			
<b>19. Accident Location</b> 30 - Mill/Prep Plant								<b>20. Mining Height</b> 52 Feet 0 Inches	
<b>21. Nonfatal Injuries</b> 0		<b>22. Fatal Injuries</b> 1							
<b>23. Victims Information</b>									
Gregory L Solomon									
<b>a) First Name</b> Gregory	<b>a) MI</b> L	<b>a) Last Name</b> Solomon		<b>b) Age</b> 38	<b>c) Regular Job Title</b> Ground Man		<b>d) Activity at Time of Accident</b> Ground Man		<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>									
<b>a) Total Experience</b> 0 Years 32 Weeks 1 Days		<b>b) Experience at the Mine</b> 0 Years 32 Weeks 1 Days		<b>c) Experience at the Activity at the Time of the Accident</b> 0 Years 32 Weeks 1 Days			<b>d) Experience with Contractor</b> Years Weeks Days		
<b>25. Autopsy Performed</b> Yes		<b>If Yes, Location</b> Farmington, MO							
<b>26. Mine Telephone No.</b> (573) 438-7342									
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner was killed when he became entangled in a fluted tail pulley.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
<b>28. Equipment Manufacturer</b> Not listed Belt conveyor not commercially manufact.					<b>29. Model</b> N/A				
<b>30. District</b> C1000 - Madisonville District					<b>32. Field Office</b> C1004 - Rolla MO Field Office			<b>33. Event Number</b> 6490311	
<b>34. Accident Investigator</b>									
<b>First Name</b> Keith		<b>MI</b> Stephen		<b>Last Name</b> Markeson					
<b>35. MSHA Person Notified</b>									
<b>First Name</b> William		<b>MI</b> L		<b>Last Name</b> Barnwell		<b>Date/Time Notified</b> 02/08/2021 3:11 PM			
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>			<b>Date Prepared</b>				
		<b>Full Name</b> Keith Stephen Markeson			02/08/2021				
<b>38. Reason for Amendment</b>									