Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 06/14/2021

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 06/09/2021 2:13 PM	4. Date/Time of Death 06/09/2021 4:04 PM	5. Fatal Case No FAI-6855110-2		
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Stillwater Mining Company STILLWATER MINE Sibanye Stillwater Limited					
, ,	County Stillwater	c) State MT	8. Mine ID Number 24-01490	9. Union Yes		
10. Primary Mineral Mined Platinum Group Ore Mining		11. Number of Employees a) Total b) Underg	ground c) Open Pit/Quarry	d) Mill/Prep Plant e) Other 52 0		
12. Contractor Name			13. Contractor Union	14. Contractor ID Number		
15. Contractor Address a) City	b) County	c) State	d) Zip Code			
16. Number of Contractor Employ a) Total	ees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other		
17. Number of Persons in Mine at a) Mine Employees	Time of Accident b) Contractor Employees 46	18. Number of Persons Unaccoun a) Mine Employees	ted for b) Contractor Employees			
19. Accident Location 01 - Underground				20. Mining Height Feet Inches		
21. Nonfatal Injuries	22. Fatal Injuries					
23. Victims Information						
Jerry W Ashlock						
	(1) (1) (1)	1 14				
a) First Name a) MI a) La	st Name b) Age c) Regular Jo shlock 55 Developme	, ,	t Time of Accident ent General Foreman	Employee Mine Employee		
a) First Name a) MI a) La	b) Experience at the Mine	, ,	ent General Foreman Time of the Accident d) Exp			
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience	b) Experience at the Mine	nt General Foreman Developm c) Experience at the Activity at the	ent General Foreman Time of the Accident d) Exp	Mine Employee		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed	b) Experience at the Mine 0 Years 9 Weeks 2 Days	nt General Foreman Developm c) Experience at the Activity at the	ent General Foreman Time of the Accident d) Exp	Mine Employee		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included)	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days	ent General Foreman Time of the Accident d) Exp 0 Ye	Mine Employee		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included Two miners were fatally injured to the second sec	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact to when the Kobota mantrip they were tr	nt General Foreman Developm c) Experience at the Activity at the 0 Years 9 Weeks 2 Days	ent General Foreman Time of the Accident d) Exp 0 Ye	Mine Employee perience with Contractor ears 0 Weeks 0 Days		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included Two miners were fatally injured to the information provided in this	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact to when the Kobota mantrip they were tr	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days ocation in the mine, and status and reaveling was struck by a 20 ton locomot	ent General Foreman Time of the Accident d) Exp 0 Ye	Mine Employee perience with Contractor ears 0 Weeks 0 Days		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included to the information provided in this cause of the accident.	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact to when the Kobota mantrip they were tr	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days ocation in the mine, and status and reaveling was struck by a 20 ton locomot NLY and does not represent final determined to the status and reaveling was struck by a 20 ton locomot NLY and does not represent final determined to the status and represent final determined to the	ent General Foreman Time of the Accident d) Exp 0 Ye ecovery operations) ive. mination regarding the nature of the in	Mine Employee perience with Contractor ears 0 Weeks 0 Days		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included to the information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact to when the Kobota mantrip they were tr	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days coation in the mine, and status and reaveling was struck by a 20 ton locomoto NLY and does not represent final determined to 1000	ent General Foreman Time of the Accident d) Exp 0 Ye ecovery operations) ive. mination regarding the nature of the in	Mine Employee perience with Contractor pears 0 Weeks 0 Days acident or conclusions regarding the		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included to the information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District M6000 - Denver District 34. Accident Investigator First Name	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact Ic when the Kobota mantrip they were traction to the company data Company	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days coation in the mine, and status and reaveling was struck by a 20 ton locomoto NLY and does not represent final determined to 1000	ent General Foreman Time of the Accident d) Exp 0 Yes 1 to 2 to 3	Mine Employee perience with Contractor pears 0 Weeks 0 Days acident or conclusions regarding the		
a) First Name a) MI a) La Jerry W As 24. Mining Experience a) Total Experience 24 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (included to the information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District M6000 - Denver District 34. Accident Investigator First Name Thaddeus 35. MSHA Person Notified First Name	b) Experience at the Mine 0 Years 9 Weeks 2 Days If Yes, Location de equipment involved, the exact lewhen the Kobota mantrip they were transition in the first produce is based on preliminary data Communication. MI Last Name J Sichmeller MI Last Name	c) Experience at the Activity at the 0 Years 9 Weeks 2 Days coation in the mine, and status and represent final determined and the status and represent final determined and the status and represent final determined and status and represent final determined and for the status and for the status and for the status and for the status and for the	ent General Foreman Time of the Accident d) Exp 0 Yes 1 to 2 to 3	Mine Employee perience with Contractor pears 0 Weeks 0 Days acident or conclusions regarding the		

Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 06/14/2021

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 06/09/2021 2:13 PM	4. Date/Time of Death 06/09/2021 4:04 PM	5. Fatal Case No FAI-68551101		
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Stillwater Mining Company STILLWATER MINE Sibanye Stillwater Limited					
	County Stillwater	c) State MT	8. Mine ID Number 24-01490	9. Union Yes		
10. Primary Mineral Mined Platinum Group Ore Mining		11. Number of Employees a) Total b) Under	ground c) Open Pit/Quarry	d) Mill/Prep Plant e) Other 52 0		
12. Contractor Name		'	13. Contractor Union	14. Contractor ID Number		
15. Contractor Address a) City	b) County	c) State	d) Zip Code			
16. Number of Contractor Employ a) Total	ees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other		
17. Number of Persons in Mine at a) Mine Employees	Time of Accident b) Contractor Employees 46	18. Number of Persons Unaccour a) Mine Employees	nted for b) Contractor Employees			
19. Accident Location 01 - Underground				20. Mining Height Feet Inches		
21. Nonfatal Injuries	22. Fatal Injuries					
23. Victims Information						
Dale G Ketola						
\ =:		1 1 				
, ,		, ,	Time of Accident ent Supervisor	Employee Mine Employee		
, ,	Ketola 65 Develo		ent Supervisor ne Time of the Accident d) Ex			
Dale G 24. Mining Experience a) Total Experience	Ketola 65 Develo	ppment Supervisor Developme c) Experience at the Activity at the	ent Supervisor ne Time of the Accident d) Ex	Mine Employee perience with Contractor		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days	b) Experience at the Mine 12 Years 29 Weeks 2 Days	ppment Supervisor Developme c) Experience at the Activity at the	ent Supervisor ne Time of the Accident d) Ex	Mine Employee perience with Contractor		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (inclu	ketola 65 Develor b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I	ppment Supervisor Developme c) Experience at the Activity at the	nt Supervisor ne Time of the Accident d) Ex 0 \	Mine Employee perience with Contractor		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (inclutive miners were fatally injured to the second s	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days	net Supervisor ne Time of the Accident d) Ex 0 N ecovery operations)	Mine Employee perience with Contractor /ears 0 Weeks 0 Days		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (inclutive miners were fatally injured of the information provided in this	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days location in the mine, and status and recovering was struck by a 20 ton locomorphism.	net Supervisor ne Time of the Accident d) Ex 0 N ecovery operations)	Mine Employee perience with Contractor /ears 0 Weeks 0 Days		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (incluit Two miners were fatally injured of the information provided in this cause of the accident.	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days Ocation in the mine, and status and reveling was struck by a 20 ton locomorphic DNLY and does not represent final determined.	ne Time of the Accident d) Ex 0 Y	Mine Employee perience with Contractor /ears 0 Weeks 0 Days		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (incluing Two miners were fatally injured on the information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days Ocation in the mine, and status and recording was struck by a 20 ton locomol DNLY and does not represent final determination. 29. Model TOT200D-FP 32. Field Office	ne Time of the Accident d) Ex 0 Y	Mine Employee perience with Contractor rears 0 Weeks 0 Days ncident or conclusions regarding the		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (incluing Two miners were fatally injured on the information provided in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District M6000 - Denver District 34. Accident Investigator First Name	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to notice is based on preliminary data of the motive of the second of the	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days Ocation in the mine, and status and recording was struck by a 20 ton locomol DNLY and does not represent final determination. 29. Model TOT200D-FP 32. Field Office	rent Supervisor The Time of the Accident d) Experiment (a) Experiment (b) Experiment (c) Experi	Mine Employee perience with Contractor rears 0 Weeks 0 Days ncident or conclusions regarding the		
Dale G 24. Mining Experience a) Total Experience 42 Years 0 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (406) 373-8700 27. Description of Accident (incluim Two miners were fatally injured in this cause of the accident. 28. Equipment Manufacturer Not listed Brookville 30. District M6000 - Denver District 34. Accident Investigator First Name Thaddeus 35. MSHA Person Notified First Name	b) Experience at the Mine 12 Years 29 Weeks 2 Days If Yes, Location de equipment involved, the exact I when the Kobota mantrip they were to notice is based on preliminary data of the significant of the	c) Experience at the Activity at the 12 Years 29 Weeks 2 Days Ocation in the mine, and status and recording was struck by a 20 ton locomol DNLY and does not represent final determination. 29. Model TOT200D-FP 32. Field Office M6821 - Helena MT Field Office	rent Supervisor The Time of the Accident d) Experiment (a) Experiment (b) Experiment (c) Experi	Mine Employee perience with Contractor rears 0 Weeks 0 Days ncident or conclusions regarding the		