# **Preliminary Report of Accident**

## U.S. Department of Labor Mine Safety and Health Administration

### PR001 03/10/2021

1. Accident Type F - Fatal Injury	2. Accident Classification 17 - Machinery	3. Date/Time of Accident 03/05/2021 10:30 AM	4. Date/Time of Death 03/05/2021 3:00 PM	<b>5. Fatal Case No</b> FAI-6840627-1
6. Mine Information	-	-		
a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Dave Clinard Truck Service Inc Otter Creek Sand & Gravel Inc Dave Clinard			
7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State	11-01131	No
MT. STERLING	Fulton	IL		
10. Primary Mineral Mined		11. Number of Employees		:
Construction Sand & Gravel Mir	ning, N.E.C.		derground c) Open Pit/Quarry	d) Mill/Prep Plant e) Other
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address				
a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employ	/ees			
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at a) Mine Employees	t Time of Accident b) Contractor Employees	18. Number of Persons Unacco a) Mine Employees	ounted for b) Contractor Employees	
19. Accident Location				20. Mining Height Feet Inches
06 - Dredge Mining				reet inches
21. Nonfatal Injuries	22. Fatal Injuries			reet inches
	-			reet inches
21. Nonfatal Injuries	-			reet inches
21. Nonfatal Injuries  23. Victims Information  Roger D Branscum	1	ular Job Title d) Activity at	Time of Accident	
21. Nonfatal Injuries  23. Victims Information  Roger D Branscum	1 a) Last Name b) Age c) Regu	<b>ular Job Title d) Activity at</b> e Manager Operating E	Time of Accident Excavator	Employee Mine Employee
21. Nonfatal Injuries  23. Victims Information  Roger D Branscum  a) First Name a) MI a	a) Last Name b) Age c) Regularies Branscum 63 Mine b) Experience at the Mine		Excavator the Time of the Accident d) E	Employee
21. Nonfatal Injuries  23. Victims Information  Roger D Branscum  a) First Name a) MI a Roger D  24. Mining Experience a) Total Experience	a) Last Name b) Age c) Regularies Branscum 63 Mine b) Experience at the Mine	e Manager Operating E  c) Experience at the Activity at	Excavator the Time of the Accident d) E	Employee Mine Employee Experience with Contractor

(309) 759-4293

#### 27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

The victim was operating a John Deere 225C LC RTS excavator along an elevated roadway running adjacent to the dredge pond. The ground under the track on one side of the excavator sloughed off and the excavator overturned falling approx. 13 foot to the edge of the pond where the sand slid into the pond taking the excavator into the pond. The miner was found inside the cab by divers after their arrival on site.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer John Deere			29. Model 225C LC RTS	
30. District M4000 - Duluth District			32. Field Office M4821 - Peru IL Field Office	33. Event Number 6840627
34. Accident Investigator				·
First Name	MI	Last Name		
James	Α	Hines		
35. MSHA Person Notified				
First Name	MI	Last Name	Date/Time Notified	
Gerald	D	Holeman	03/05/2021 12:10 PM	
36. Type of Report	37. Name of F	Preparer		
Initial	Full Name	•	Date Prepared	
	James A Hines		03/05/2021	