

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 12/09/2022

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 12/06/2022 1:30 PM		<b>4. Date/Time of Death</b> 12/06/2022 1:30 PM		<b>5. Fatal Case No</b> FAI-7028168-1		
<b>6. Mine Information</b>										
<b>a) Mining Company Name:</b>		The Doe Run Company								
<b>b) Mine Name:</b>		Viburnum #35 (Casteel Mine)								
<b>c) Parent of Mining Company:</b>		Renco Group								
<b>7. Mine Location Information</b>					<b>8. Mine ID Number</b>		<b>9. Union</b>			
<b>a) City</b> VIBURNUM		<b>b) County</b> Iron		<b>c) State</b> MO		23-01800		No		
<b>10. Primary Mineral Mined</b> Lead-Zinc Ore Mining, N.E.C.				<b>11. Number of Employees</b>						
				<b>a) Total</b> 103	<b>b) Underground</b> 101	<b>c) Open Pit/Quarry</b>		<b>d) Mill/Prep Plant</b>	<b>e) Other</b> 2	
<b>12. Contractor Name</b>					<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>			
<b>15. Contractor Address</b>										
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>		
<b>16. Number of Contractor Employees</b>										
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>		<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>					
<b>a) Mine Employees</b> 57		<b>b) Contractor Employees</b>			<b>a) Mine Employees</b>		<b>b) Contractor Employees</b>			
<b>19. Accident Location</b> 01 - Underground								<b>20. Mining Height</b> 18 Feet    Inches		
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
Hagen M Barton										
<b>a) First Name</b> Hagen	<b>a) MI</b> M	<b>a) Last Name</b> Barton		<b>b) Age</b> 41	<b>c) Regular Job Title</b> Charger			<b>d) Activity at Time of Accident</b> Loading Explosives into Blastholes		<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>										
<b>a) Total Experience</b> 16 Years 32 Weeks Days		<b>b) Experience at the Mine</b> 15 Years 23 Weeks Days			<b>c) Experience at the Activity at the Time of the Accident</b> 11 Years 51 Weeks Days			<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days		
<b>25. Autopsy Performed</b> Yes		<b>If Yes, Location</b> Farmington, Missouri								
<b>26. Mine Telephone No.</b> (573) 244-5261 x 4419										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner was operating a diesel tractor underground when the tractor hit a rib. The miner was thrown from the tractor and was crushed under a rear tire of the tractor.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Getman				<b>29. Model</b> A64						
<b>30. District</b> C1000 - Madisonville District				<b>32. Field Office</b> C1004 - Rolla MO Field Office			<b>33. Event Number</b> 7028168			
<b>34. Accident Investigator</b>										
<b>First Name</b> Jeremy		<b>MI</b> D	<b>Last Name</b> Kennedy							
<b>35. MSHA Person Notified</b>										
<b>First Name</b> Louis		<b>MI</b> F.	<b>Last Name</b> Adams			<b>Date/Time Notified</b> 12/06/2022 2:14 PM				
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b> <b>Full Name</b> Curtis R Hardison			<b>Date Prepared</b> 12/07/2022					
<b>38. Reason for Amendment</b>										