

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 05/25/2022

1. Accident Type F - Fatal Injury	2. Accident Classification 17 - Machinery	3. Date/Time of Accident 02/28/2022 5:00 AM	4. Date/Time of Death 02/28/2022 5:00 AM	5. Fatal Case No FAI-7016523-1
6. Mine Information				
a) Mining Company Name: Ramaco Resources, LLC		b) Mine Name: Berwind Deep Mine		
c) Parent of Mining Company: Ramaco Resources Inc				
7. Mine Location Information			8. Mine ID Number 46-09533	9. Union No
a) City Berwind	b) County Mcdowell	c) State WV		
10. Primary Mineral Mined Bituminous Coal Underground Mining		11. Number of Employees		
		a) Total 51	b) Underground 46	c) Open Pit/Quarry 0
			d) Mill/Prep Plant 0	e) Other 5
12. Contractor Name GMS Mine Repair			13. Contractor Union No	14. Contractor ID Number MVK
15. Contractor Address				
a) City Mt. Lake Park		b) County	c) State MD	d) Zip Code 21550
16. Number of Contractor Employees				
a) Total 3		b) Underground 3	c) Open Pit/Quarry 0	d) Mill/Prep Plant 0
			e) Other 0	
17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for		
a) Mine Employees 12		b) Contractor Employees 2		
		a) Mine Employees 0		b) Contractor Employees 0
19. Accident Location 01 - Underground				20. Mining Height 6 Feet 0 Inches
21. Nonfatal Injuries 0	22. Fatal Injuries 1			

23. Victims Information

Steven Hively						
a) First Name Steven	a) MI	a) Last Name Hively	b) Age 52	c) Regular Job Title Project Manager	d) Activity at Time of Accident Tramming Drill Machine	Employee Contractor Employee
24. Mining Experience						
a) Total Experience 20 Years 0 Weeks 0 Days		b) Experience at the Mine 0 Years 1 Weeks 0 Days		c) Experience at the Activity at the Time of the Accident 0 Years 3 Weeks 0 Days		d) Experience with Contractor 5 Years 8 Weeks 0 Days
25. Autopsy Performed No						

26. Mine Telephone No.

(681) 225-0006

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

A contract miner was tramming a single boom face drill to the surface when he became pinned between the drill and the coal rib.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Fletcher		29. Model 3411-RE		
30. District C1200 - Pineville District		32. Field Office C1203 - Logan WV Field Office		33. Event Number 7016523
34. Accident Investigator				
First Name	MI	Last Name		
35. MSHA Person Notified				
First Name David	MI	Last Name Thacker	Date/Time Notified 02/28/2022 5:58 AM	
36. Type of Report Initial	37. Name of Preparer		Date Prepared	
	Full Name Tracy F Calloway		Date Prepared 03/01/2022	

38. Reason for Amendment