Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration



PR001 12/18/2023

1. Accident Type F - Fatal Injury	2. Accident Classification 17 - Machinery	3. Date/Time of Accident 12/14/2023 7:34 AM		4. Date/Time of Death 12/14/2023 7:34 AM		5. Fatal Case No FAI-6932874-1	
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Bison Materials LLC Bison No 1 Spencer Gene Hopper						
7. Mine Location Information a) City BARTLESVILLE	b) County c) Washington	State OK	8. Mine ID Number 34-02093			9. Union No	
10. Primary Mineral Mined Crushed & Broken Limestone Mining, N.E.C.		11. Number of Employees a) Total b) Underground 15		d c) Open Pit/Quarry 15		d) Mill/Prep Plant	e) Other
12. Contractor Name				13. Contractor Union		14. Contractor ID Nu	mber
15. Contractor Address a) City	b) County	c) State		d) Zip Code			
16. Number of Contractor Employees a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other							
17. Number of Persons in Mine at Time of Accident a) Mine Employees b) Contractor Employees 10 18. Number of Persons Unaccounted for a) Mine Employees b) Contractor Employees 0							
19. Accident Location 03 - Open Pit						20. Mining Height Feet Inches	
21. Nonfatal Injuries	22. Fatal Injuries						
23. Victims Information							
Jimmie D Hoppock							
a) First Name a Jimmie) MI a) Last Name D Hoppock		gular Job Title ant Maintenance	d) Activity at Time of Acc	ident	Employee Mine Employee	
24. Mining Experience a) Total Experience b) Experience at the Mine 11 Years 12 Weeks 4 Days c) Experience at the Activity at the Time of the Accident 11 Years 12 Weeks 4 Days 12 Weeks 4 Days C) Experience at the Activity at the Time of the Accident 13 Years 12 Weeks 4 Days Years Weeks Days							
25. Autopsy Performed Yes	If Yes, Location Tulsa, Oklahoma						
26. Mine Telephone No. (918) 534-9992							
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner died while performing maintenance work on a feed plate. While attempting to move a chute to gain access to the feed plate, the chute moved, and pinned the miner between a handrail and the chute.							
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding							
thecause of the accident. 28. Equipment Manufacturer Not Reported		29. Model					
30. District M5000 - Dallas District		32. Field Office M5861 - Norr	man OK Field Offic	e		33. Event Number 6932874	
34. Accident Investigator First Name Brody	MI Last Name Haddock						
35. MSHA Person Notified First Name Nick	MI Last Name Gutierrez		Date/Time Not 12/14/2023 7:1				
36. Type of Report Initial	37. Name of Preparer Full Name Brody Haddock	Date P 12/14/2	repared 2023				
38. Reason for Amendment							