## **Preliminary Report of Accident**

## U.S. Department of Labor Mine Safety and Health Administration

## PR001 02/10/2023

1. Accident Type F - Fatal Injury	2. Accident Classification 01 - Electrical	3. Date/Time of Accident 02/06/2023 3:45 PM	4. Date/Time of Death 02/07/2023 9:19 AM	<b>5. Fatal Case No</b> FAI-6935003-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Rogers Group Inc Greenbrier Quarry Rogers Group Inc			
7. Mine Location Information a) City Greenbriar	<b>b) County</b> Faulkner	c) State AR	8. Mine ID Number 03-00855	9. Union No
10. Primary Mineral Mined		11. Number of Employees		
Crushed & Broken Sandstone Mining		<b>a) Total b) Under</b> 13 0	ground c) Open Pit/Quarry 6	d) Mill/Prep Plant e) Other
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address a) City	b) County	c) State	d) Zip Code	
16. Number of Contractor Employa) Total	ees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at Time of Accident a) Mine Employees b) Contractor Employees a) Mine Employees b) Contractor Employees b) Contractor Employees 0				
19. Accident Location 03 - Open Pit				20. Mining Height 0 Feet Inches
21. Nonfatal Injuries	22. Fatal Injuries			1
23. Victims Information	I			
Javier Regalado-Cano				
a) First Name a) MI a) Last Name b) Age c) Regular Job Title d) Activity at Time of Accident Employee  Javier Regalado-Cano 61 Haul Truck Operator Operating a Haul Truck Mine Employee				
24. Mining Experience a) Total Experience b) Experience at the Mine 1 Years 43 Weeks 2 Days Years 17 Weeks 3 Days C) Experience at the Activity at the Time of the Accident 1 Years 26 Weeks 3 Days Years Weeks Days 1 Years 26 Weeks 3 Days Years Weeks Days				
25. Autopsy Performed If Yes, Location				
Yes Little Rock Medical Examiner				
<b>26. Mine Telephone No.</b> (501) 679-3178				
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)  A haul truck driver raised the truck bed into an overhead 13,200V voltage power line. The driver exited the truck to extinguish a fire on the truck's tire and was electrocuted when he tried to reenter the truck.				
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.				
28. Equipment Manufacturer Caterpillar		<b>29. Model</b> 770		
30. District M5000 - Dallas District M5871 - Little Rock AR Field Office			33. Event Number 6935003	
34. Accident Investigator				
First Name	MI Last Name			
35. MSHA Person Notified				
First Name	MI Last Name			
Dwight	P Shields	02/06/2023 3:	13 PM	
36. Type of Report	37. Name of Preparer			
Initial	Full Name	Date Prepared		
	Dave E Smith	02/05/2023		
38. Reason for Amendment				