## Preliminary Report of Accident



## PR001 03/06/2023

1. Accident Type F - Fatal Injury	2. Accident Classific 17 - Machinery	ation	3. Date/Time of Accident 03/01/2023 10:30 AM	4. Date/Time of Death 03/01/2023 10:30 AM	5. Fatal Case No FAI-4408672-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Mountain Aggregate Elkhorn Stone CRH PLC	es Inc			
7. Mine Location Information a) City Elkhorn City	<b>b) Count</b> y Pike	/	c) State KY	8. Mine ID Number 15-00213	9. Union Yes
10. Primary Mineral Mined Crushed & Broken Limestone Mining, N.E.C.			11. Number of Employees a) Total b) Under 9	ground c) Open Pit/Quarry 1	<b>d) Mill/Prep Plant e) Other</b> 8 0
12. Contractor Name Bizzack Construction LLC				13. Contractor Union Yes	<b>14. Contractor ID Number</b> V409
15. Contractor Address a) City Lexington	b) (	County	<b>c) State</b> KY		
16. Number of Contractor Employe a) Total 5	Fotal b) Underground			<b>d) Mill/Prep Plant</b> 0	e) Other
17. Number of Persons in Mine ata) Mine Employees9	Time of Accident b) Contractor Employe 7	es	18. Number of Persons Unaccour a) Mine Employees 0	nted for b) Contractor Employees 0	
<b>19. Accident Location</b> 03 - Open Pit					20. Mining Height Feet Inches
<b>21. Nonfatal Injuries</b> 0	22. Fatal Injuries				
23. Victims Information					
Joshua D Coleman					
	<b>st Name b) Age</b> leman 38	c) Regular Job Bulldozer Op		sident	Employee Contractor Employee
24. Mining Experience       b) Experience at the Mine       c) Experience at the Activity at the Time of the Accident       d) Experience with Contractor         13 Years 36 Weeks 0 Days       0 Years 34 Weeks 4 Days       7 Years 20 Weeks 0 Days       0 Years 34 Weeks 4 Days					
25. Autopsy Performed	If Yes, Location				
Yes	Frankfort KY				
<b>26. Mine Telephone No.</b> (606) 754-4117					
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor employee died when the bulldozer he was operating backed over a spoil bank, left the bench area, and rolled down an embankment. The contractor employee was ejected from the bulldozer.					
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.					
28. Equipment Manufacturer Caterpillar			29. Model D8R		
30. District C0500 - Norton District			32. Field Office C0504 - Pikeville KY Field Office	e	<b>33. Event Number</b> 4408672
34. Accident Investigator First Name	МІ	Last Name			
Thomas		Bower			
35. MSHA Person Notified First Name Jeffery		<b>Last Name</b> Webb	Date/Time No 03/01/2023 10		
36. Type of Report Initial	37. Name of Prepare Full Name Thomas R Bower		Date Prepared 03/02/2023		
38. Reason for Amendment					