



Fatality Alert

MINE FATALITY – On March 22, 2023, a miner died when the personnel carrier he was riding overturned. Another miner riding on the personnel carrier accidentally actuated the emergency stop causing the personnel carrier to drift backwards down a grade. The personnel carrier struck a coal rib and overturned, pinning the victim beneath it. The victim was not riding in a designated seating area.



Best Practices

- Maintain steering and braking components.
- Perform functional tests of brakes and other safety devices during the pre-operational examination.
- Tag out and remove equipment from service when defects affecting safety are found.
- Do not exceed the maximum designed seating capacity of personnel carriers.
- Operate mobile equipment at speeds consistent with roadway conditions.
- Task train miners on all equipment they operate.

This is the 14th fatality reported in 2023, and the third classified as "Powered Haulage."

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

msha.gov | askmsha@dol.gov | @MSHA DOL