

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 03/21/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 03/09/2023 1:55 PM		4. Date/Time of Death 03/09/2023 1:55 PM		5. Fatal Case No FAI-6934008-1	
6. Mine Information									
a) Mining Company Name:		Texas Lime Company							
b) Mine Name:		Plant & Quarry							
c) Parent of Mining Company:		United States Lime & Minerals Inc							
7. Mine Location Information					8. Mine ID Number		9. Union		
a) City CLEBURNE		b) County Johnson		c) State TX		41-00072		Yes	
10. Primary Mineral Mined Crushed & Broken Limestone Mining, N.E.C.				11. Number of Employees			d) Mill/Prep Plant		e) Other
				a) Total 79	b) Underground		c) Open Pit/Quarry 11	66	2
12. Contractor Name						13. Contractor Union		14. Contractor ID Number	
15. Contractor Address									
a) City		b) County			c) State			d) Zip Code	
16. Number of Contractor Employees									
a) Total		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for				
a) Mine Employees 55		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees		
19. Accident Location 03 - Open Pit								20. Mining Height 30 Feet Inches	
21. Nonfatal Injuries 0		22. Fatal Injuries 1							
23. Victims Information									
Don W Reynolds									
a) First Name Don	a) MI W	a) Last Name Reynolds		b) Age 60	c) Regular Job Title Delivery Truck Driver		d) Activity at Time of Accident Coal Delivery to Mine Site		Employee Other Employee
24. Mining Experience									
a) Total Experience 5 Years 28 Weeks 3 Days		b) Experience at the Mine 5 Years 28 Weeks 3 Days			c) Experience at the Activity at the Time of the Accident 5 Years 28 Weeks 3 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days	
25. Autopsy Performed Yes		If Yes, Location							
26. Mine Telephone No. (817) 641-4433									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A truck driver died when he was run over by a tractor-trailer. A front-end loader struck the rear of the tractor-trailer, causing the tractor-trailer to move forward and strike the victim. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Mack					29. Model P164T				
30. District M5000 - Dallas District					32. Field Office M5671 - Dallas TX Field Office			33. Event Number 6934008	
34. Accident Investigator									
First Name Brody		MI		Last Name Haddock					
35. MSHA Person Notified									
First Name Brett		MI		Last Name Barrick			Date/Time Notified 03/09/2023 3:12 PM		
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name Brody Haddock			03/09/2023				
38. Reason for Amendment									