

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 02/04/2025

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 01/30/2025 3:30 PM		4. Date/Time of Death 01/30/2025 3:30 PM		5. Fatal Case No FAI-F012FA8-1			
6. Mine Information											
a) Mining Company Name:		Salado Operations									
b) Mine Name:		Salado Operations, Florence									
c) Parent of Mining Company:		Dos Rios Partners - A, LP et al									
7. Mine Location Information			8. Mine ID Number		9. Union						
a) City FLORENCE			b) County Williamson		c) State TX		41-04216		No		
10. Primary Mineral Mined Dimension Limestone Mining				11. Number of Employees							
				a) Total 72		b) Underground		c) Open Pit/Quarry 66		d) Mill/Prep Plant 0	
								e) Other 6			
12. Contractor Name						13. Contractor Union		14. Contractor ID Number			
15. Contractor Address											
a) City						b) County		c) State		d) Zip Code	
16. Number of Contractor Employees											
a) Total						b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant	
										e) Other	
17. Number of Persons in Mine at Time of Accident						18. Number of Persons Unaccounted for					
a) Mine Employees 66						b) Contractor Employees					
						0					
19. Accident Location 03 - Open Pit								20. Mining Height Feet Inches			
21. Nonfatal Injuries				22. Fatal Injuries 1							
23. Victims Information											
Luis G Sanchez-Robles											
a) First Name Luis		a) MI G		a) Last Name Sanchez-Robles		b) Age 22		c) Regular Job Title Thin Verner Saw Operator		d) Activity at Time of Accident Moving Stone	
										Employee Mine Employee	
24. Mining Experience				25. Autopsy Performed							
a) Total Experience Years 32 Weeks 3 Days				b) Experience at the Mine Years 32 Weeks 3 Days				c) Experience at the Activity at the Time of the Accident Years 32 Weeks 3 Days			
								d) Experience with Contractor Years Weeks			
				If Yes, Location							
26. Mine Telephone No.											
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner died when a front-end loader operator unknowingly lowered the pallet of stone onto the victim. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>											
28. Equipment Manufacturer Caterpillar						29. Model 924H CAT0924HHHC00568					
30. District M5000 - Dallas District						32. Field Office M5671 - Dallas TX Field Office				33. Event Number F012FA8	
34. Accident Investigator											
First Name James						MI		Last Name Redwine			
35. MSHA Person Notified											
First Name Tommy						MI D		Last Name Fitzgerald		Date/Time Notified 01/30/2025 4:24 PM	
36. Type of Report Initial				37. Name of Preparer				Date Prepared			
				Full Name James Redwine				01/30/2025			
38. Reason for Amendment											