



Fatality Alert

MINE FATALITY – On July 12, 2025, a delivery truck driver died when the truck he was driving traveled off the road and crashed into a ravine.



Best Practices

- Maintain control of mobile equipment and follow all posted speed limit and warning signs.
- Ensure berms and guardrails are at least as high as the mid-axle height of the largest mobile equipment using the roadway.
- Ensure braking systems can stop and hold the equipment with its typical load on the maximum grade it travels.
- Always wear a seatbelt while operating mobile equipment.
- Perform thorough pre-operational inspections of mobile equipment. Correct any defects that create a hazard.

This is the 16th fatality reported in 2025, and the seventh classified as "Powered Haulage."

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

msha.gov | askmsha@dol.gov | @MSHA DOL