

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 01/13/2026

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 01/08/2026 11:33 AM	4. Date/Time of Death 01/08/2026 11:33 AM	5. Fatal Case No FAI-F02982-1
<b>6. Mine Information</b> <p>a) Mining Company Name: Ash Grove Cement South Texas LLC b) Mine Name: Hunter Cement Plant c) Parent of Mining Company: CRH PLC</p>				
7. Mine Location Information a) City OVERLAND PARK	b) County Comal	c) State TX	8. Mine ID Number 41-02820	9. Union No
10. Primary Mineral Mined Hydraulic Cement	11. Number of Employees a) Total 175		b) Underground 0	c) Open Pit/Quarry 0
12. Contractor Name		13. Contractor Union		14. Contractor ID Number
<b>15. Contractor Address</b> a) City		b) County	c) State	d) Zip Code
<b>16. Number of Contractor Employees</b> a) Total		b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant
<b>17. Number of Persons in Mine at Time of Accident</b> a) Mine Employees		<b>18. Number of Persons Unaccounted for</b> a) Mine Employees b) Contractor Employees		
<b>19. Accident Location</b> 00 - Other Ore stockpile		<b>20. Mining Height</b> Feet Inches		
21. Nonfatal Injuries	22. Fatal Injuries 1			

23. Victims Information

<b>Timothy J Lewey</b>						
a) First Name Timothy	a) MI J	a) Last Name Lewey	b) Age 44	c) Regular Job Title Over the road Truck Driver	d) Activity at Time of Accident Delivering core material	Employee Other Employee
<b>24. Mining Experience</b> a) Total Experience 2 Years 0 Weeks 0 Days		b) Experience at the Mine 0 Years 0 Weeks 1 Days		c) Experience at the Activity at the Time of the Accident 2 Years 0 Weeks 0 Days		d) Experience with Contractor 0 Years 0 Weeks 0
<b>25. Autopsy Performed</b> Yes		If Yes, Location Comal				

26. Mine Telephone No.  
(512) 396-4244

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

An over the road truck driver died after he became pinned between the dump bed and the frame of a truck.

*The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.*

28. Equipment Manufacturer Freightliner	29. Model 108SD		
30. District M5000 - Dallas District	32. Field Office M5671 - Dallas TX Field Office	33. Event Number F02982C	
34. Accident Investigator First Name David	MI M	Last Name Mulhollen	
35. MSHA Person Notified First Name John	MI S	Last Name Powers	Date/Time Notified 01/08/2026 12:22 PM
36. Type of Report Initial	37. Name of Preparer Full Name David M Mulhollen		
	Date Prepared 01/08/2026		
38. Reason for Amendment			