

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 09/08/2016 01:50 PM		4. Date/Time of Death 09/08/2016		5. Fatal Case No 12		
6. Mine Information :										
a) Mining Company Name Hanson Aggregates Southeast, LLC			b) Mine Name NEVERSON QUARRY			c) Parent of Mining Company Heidelberg Cement AG				
7. Mine Location :		a) City Sims		b) County Wilson		c) State NC		8. Mine ID Number: 31-00074		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN GRANITE MINI			11. Number of Mine Employees:		a) Total 14	b) Underground 0	c) Open Pit/Quarry 5		d) Mill/Prep Plant 5	e) Other 4
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total 4	b) Underground 4		c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other	
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:				
a) Mine Employees: 14		b) Contractor Employees: 4		a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries:			22. Fatal Injuries:		1					
23. Victim Information :										
a) Name Richard Smith					b) Age 58					
c) Regular Job Title: Haul Truck Operator				d) Activity at Time of Accident: Operating a Caterpillar 773E haul truck				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:	23	35	b) at the mine:	2	9	c) at activity (23d)	2	9	d) with Contractor	
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (252) 235-4162				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
The victim was operating a Caterpillar 773E haul truck returning to the pit to be loaded with shot rock. The truck veered from the right side of the haul road to the left and traveled over a berm and over the highwall. The truck landed upside down approximately 200 feet below. The victim was found outside of the haul truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 773E		
30. District: M3000 Southeastern		32. Field Office: Sanford NC			33. Event Number: 6714134
34. Accident Investigator: Jeff Phillips			35. MSHA Person Notified: David Allen		Date 09/08/2016
					Time 02:25 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: David Allen			
		Date 09/09/2016			
38. Reason For Amendment:					