

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock/Material		3. Date/Time of Accident 03/14/2017 05:30 AM		4. Date/Time of Death 03/14/2017 05:30 AM		5. Fatal Case No 2		
6. Mine Information :										
a) Mining Company Name Trinity Materials, Inc.			b) Mine Name Cottonwood #1204			c) Parent of Mining Company Trinity Industries Inc				
7. Mine Location :		a) City Rosser		b) County Kaufman		c) State TX		8. Mine ID Number: 41-04553		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 30	b) Underground	c) Open Pit/Quarry 28	d) Mill/Prep Plant	e) Other 2	
12. Contractor Name: Capricorn Trucking						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:			a) City Garland		b) County Dallas		c) State TX		d) Zip Code 75044	
16. Number of Contractor Employees:			a) Total 1	b) Underground		c) Open Pit/Quarry 1	d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 30		b) Contractor Employees: 1			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height: Feet Inches	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)			
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Julio C. Flores			b) Age 52							
c) Regular Job Title: Independent Owner/Oper. Truck Driver					d) Activity at Time of Accident: Dumping a load of sand					
<input checked="" type="checkbox"/> Contractor Employee										
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:	13 10 2		b) at the mine:	7 15 2		c) at activity (23d)	13 10 2		d) with Contractor	
25. Autopsy Performed: If Yes, Location YES Dallas County Medical Examiner						26. Mine Telephone No.: (903) 496-8890				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
 There were no witnesses to the accident. The victim, an independent owner/operator, appears to have walked behind the end-dump trailer while it was being raised and was engulfed by the sand as it came out in the excess dumping area. The truck had been loaded with 27.5 tons of concrete sand. Mine management became aware of the missing driver at approximately 10:45 am (CST) and began a search. Mine employees began digging in the pile of sand behind the truck and the victim was discovered at approximately 11:43 am (CST).

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Kenworth				29. Model: CMC Aluminum			
30. District: M5000 South Central		32. Field Office: Dallas TX			33. Event Number: 6735372		
34. Accident Investigator: Homer A. Pricer			35. MSHA Person Notified: Laurence Dunlap		Date 03/14/2017	Time 11:40 AM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Elwood M. Burriss				Date 03/16/2017	
38. Reason For Amendment:							