

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 10/11/2018 01:55 PM		4. Date/Time of Death 10/11/2018 03:03 PM		5. Fatal Case No 11		
6. Mine Information :										
a) Mining Company Name Georgia Stone Industries, Inc.			b) Mine Name Jet Mist tm Quarry			c) Parent of Mining Company Antonio C Ramos				
7. Mine Location :		a) City Rapidan		b) County Culpeper		c) State VA		8. Mine ID Number: 44-00141		9. Union: NO
10. Primary Mineral Mined: DIMENSION GRANITE MINING			11. Number of Mine Employees:		a) Total 12	b) Underground 0	c) Open Pit/Quarry 6		d) Mill/Prep Plant 0	e) Other 6
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 11		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility					25	0	
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Rony Gustavo Acosta Ordonez					b) Age 26					
c) Regular Job Title: Laborer				d) Activity at Time of Accident: Opening Block Slab of Granite				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:		3 22 2		b) at the mine:		0 48 0		c) at activity (23d)		
						0 46 6		d) with Contractor		
25. Autopsy Performed: If Yes, Location YES Manassas, VA						26. Mine Telephone No.: (540) 672-3643				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A laborer (victim) was standing on top of a freshly cut block of granite (approximately 20-feet tall by 35-feet wide by 4-feet thick and weighing an estimated 150 tons) along the south facing high wall between the top and first level of the quarry. As water was being applied to the bladders between the rock and high wall to move the rock, the block slid out at the bottom causing the miner to lose his balance and fall between the block and the high wall causing fatal injuries.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M2000 Northeastern		32. Field Office: Staunton VA				33. Event Number: 6815653	
34. Accident Investigator: Michael J. Wynkoop			35. MSHA Person Notified: Joseph H. Bosley		Date 10/11/2018	Time 02:00 PM	
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Joseph M. Denk				Date 10/23/2018	

38. Reason For Amendment:

Additional information found during the accident investigation resulted in revisions to the following: Item 24 a) and Item 24 c).