PR001
08-Nov-18

1. Accident Type:

Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

2. Accident Classification 3. Date/Time of Accident 4. Date/Time of Death

Fatal Injury	Powered Haulage			10/19/2018	03:00 PN	1 10/	19/2018 0	3:00 PM	1	9	
6. Mine Information :											
a) Mining Company Name b) Mine Name				c) Parent of Mining Company							
Montana Rockworks Inc.		MCGREGOR		Brad Mercord; Bill Carter							
7. Mine Location : a) City b) G		b) Co	ounty c) State			8. Mine ID Number:			9. Union:		
Marion Flathea		Flathead		MT			24-02226			NO	
10. Primary Mineral Mined:		11. Number of Mine	a) Total	b) Underground	c) Open Pi	it/Quarry	Quarry d) Mill/Prep Plant		e)	Other	
DIMENSION STONE MIN	DIMENSION STONE MINING, N.E.C.		Employees: 11			11		0		0	
12. Contractor Name:					13. U	nion		14. Contrac	tor ID Nu	nber:	
15. Contractor Address:	a) City		l	b) County c) State			tate	d) Zip Code			
16. Number of Contractor Employees: a) Total b) Under			Underground	d c) Open Pit/Quarry			d) Mill/Prep Plant e) Other				
17. Number of Persons in Mine at Time of Accident: 18. Number of Persons United States and States					Persons Una	ccounted F	For:				
a) Mine Employees: 1 b) Contractor Employees:				a) Mine Employees: 0 b) Contractor Employees: 0							
19) Location of Accident				ce Mining	30-Mill/Pre	n Dlant		r (specify)		ning Height:	
					-		Othe	r (specify)	Feet	Inches	
02-Surface at Underground 06-Dredge Mining 08-Retreat Mining 99-Office Facility											
21. Nonfatal Injuries:	22. Fat	al Injuries: 1									
23. Victim Information : a) Name b) Age											
	Jerry E	Baller		63							
c) Regular Job Title: d) Activity at Time of Accident:							XM	ine Emp	oyee		
Quarry Manager	arry Manager Operating Haul Truck										
24. Experience : Years Weeks Days Years Weeks Days					Years Wee	•			Years Wee	ks Days	
a) Total: 17 2	-	at the mine: 17 26	5 4 c) a	at activity (23d)	17 2	-	,	Contractor	0 0	0	
25. Autopsy Performed: If Yes, Location					26. Mi	26. Mine Telephone No.:					
YES Missoula, M	Г						(406)	752-7625			

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A quarry manager with 17 years of experience was operating a 30-ton Volvo Haul truck to transport it off-site when he was fatally injured. The victim was moving the haul truck down a steep grade, around a turn, when the haul truck traveled through a berm and off a short drop-off. The victim was found several hours later by the owner of the company in the haul truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Volvo		29. Model: A30C			
30. District: M6000 Rocky Mountain	32. Field Office: Helena MT	33. Event Number: 6777762			
34. Accident Investigator:	35. MSHA Person Notified:	Date Time 10/19/2018 11:45 PM			
Ernesto Vasquez 36. Type of Report:	Sidney J. Garay 37. Name of Preparer and Date Prepared:	10/19/2018 11:45 PM Date			
Initial	Peter Del Duca	10/24/2018			

38. Reason For Amendment:



5. Fatal Case No