Preliminary Report of Accident PR001 11/07/2019

U.S. Department of Labor Mine Safety and Health Administration



1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 11/05/2019 9:35 AM	4. Date/Time of Death 11/05/2019 9:35 AM	5. Fatal Case No 21
6. Mine Information a) Mining Company Name: ArcelorMittal Minorca Mine Inc b) Mine Name: ArcelorMittal Minorca Mine Inc c) Parent of Mining Company: ArcelorMittal USA LLC				
7. Mine Location Information a) City VIRGINIA	b) County St Louis	c) State MN	8. Mine ID Number 21-02449	9. Union Yes
10. Primary Mineral Mined Iron Ore Mining, N.E.C.		11. Number of Employeesa) Totalb) Undergroundc) Open Pit/Quarry353127		d) Mill/Prep Plant e) Other 226
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address a) City	b) County	c) State	d) Zip Code	1
16. Number of Contractor Employ a) Total	yees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
17. Number of Persons in Mine at Time of Accident 18. Number of Persons Unaccounted for a) Mine Employees b) Contractor Employees a) Mine Employees b) Contractor Employees 178 178 b) Contractor Employees b) Contractor Employees				
19. Accident Location 03 - Open Pit		1		20. Mining Height Feet Inches
21. Nonfatal Injuries 22. Fatal Injuries 1 1				
23. Victims Information	1			
Kenneth L. Mattson				
a) First Name a) MI a Kenneth L.		, ,	Time of Accident intenance vehicle	Employee Mine Employee
24. Mining Experience b) Experience at the Mine c) Experience at the Activity at the Time of the Accident d) Experience with Contractor 15 Years 26 Weeks Days 15 Years 26 Weeks Days 13 Years 51 Weeks Days 0 Years 0 Weeks 0 Days				
25. Autopsy Performed If Yes, Location				
Yes	Yes Ramsey County, Minnesota			
26. Mine Telephone No. (218) 749-5910				
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A mobile maintenance mechanic was traveling east on the pit haulage road when the service truck he was operating left the roadway, contacted a berm and flipped onto its side. The victim was ejected from from the cab of the vehicle.				
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.				
28. Equipment Manufacturer Freightliner				
30. District M4000 - North Central District -	Duluth	32. Field Office M4661 - Hibbing MN Field Office		33. Event Number 6747432
34. Accident Investigator First Name Duane	MI Last Name L Hongisto			
35. MSHA Person Notified First Name Richard	MI Last Name V Boeckermann	Date/Time No 11/05/2019 9:4		
36. Type of Report Initial	37. Name of Preparer Full Name Gerald D Holeman	Date Prepared 11/07/2019		
38. Reason for Amendment				