Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 09/24/2020

1. Accident Type F - Fatal Injury	2. Accident Classification 10 - Handtools	3. Date/Time of Accident 05/21/2020 12:30 PM	4. Date/Time of Death 05/23/2020 3:54 AM	5. Fatal Case No FAI4471998-1
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company	Bluff City Minerals LLC Bluff City Minerals	00,21,2020 12.30 T III	00/20/2020 0.0 17441	174 111 1000 1
7. Mine Location Information			8. Mine ID Number	9. Union
a) City Alton	b) County Madison	c) State IL	11-00122	Yes
10. Primary Mineral Mined Crushed & Broken Limeston	e Mining, N.E.C.		Underground c) Open Pit/Qua 29	arry d) Mill/Prep Plant e) Other
12. Contractor Name			13. Contractor Union	14. Contractor ID Number
15. Contractor Address				
a) City	b) County	c) State	d) Zip Co	ode
16. Number of Contractor Emp	loyees			
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Pla	e) Other
17. Number of Persons in Mine a) Mine Employees 18	e at Time of Accident b) Contractor Employees	18. Number of Persons Un a) Mine Employees 0	accounted for b) Contractor Employees	
19. Accident Location 01 - Underground				20. Mining Height 70 Feet 0 Inches
21. Nonfatal Injuries	22. Fatal Injuries			
23. Victims Information	·			
John C Corbin				

John C Corbin						
a) First Name John	a) MI C	a) Last Name Corbin	b) Age 60	c) Regular Job Title Plant Maintenance	d) Activity at Time of Accident Removing electric motor	Employee Mine Employee
24. Mining Expe a) Total Exper 27 Years 9	rience	, ,	nce at the N 39 Weeks I	, ,	it the Activity at the Time of the Accident eeks Days	d) Experience with Contractor Years Weeks Days
25. Autopsy Per Yes	formed	If Yes, Lo O'Fallon, I				

26. Mine Telephone No.

(618) 474-0271

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

Two miners were working to remove a 100 horsepower electric motor. They attached a 3/4 ton come-along to a steel pipe that was overhead. A chain hoist was attached between the lifting eye of the electric motor to pull the motor. As the two miners were moving the electric motor off of the motor base, the overhead steel pipe slid forward and fell striking the victim in the head and back. The victim was driven to a local hospital for treatment. The victim was treated and released from the hospital on 5/21/2020 however, he was later hospitalized on 5/23/2020 where he passed away

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer			29. Model		
30. District C0800 - Vincennes District			32. Field Office C0803 - Litchfield IL Field Office	33. Event Number 4471998	
34. Accident Investigator				·	
First Name	MI	Last Name			
Bub		Whitfield			
35. MSHA Person Notified					
First Name	MI	Last Name	Date/Time Notified		
Chad		Lampley	05/23/2020 8:09 AM		
36. Type of Report	37. Name of Prepa	rer			
Initial	Full Name		Date Prepared		
	Bub Whitfield		05/27/2020		