Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 10/15/2020

I. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date	/Time of Death	5. Fatal Case No	
F - Fatal Injury	17 - Machinery	10/09/2020 11:50 AM	10/0	9/2020 11:50 AM	FAI-4459924-1	
6. Mine Information			-			
a) Mining Company Name:	Double Mountain Mining LLC					
b) Mine Name:	Mine #3					
c) Parent of Mining Company:	Michael A Blubaugh et al					
7. Mine Location Information			8. Mine	ID Number	9. Union	
a) City	b) County	c) State	15-1	9268	No	
MIDDLESBORO	Bell	KY				
10. Primary Mineral Mined		11. Number of Employees	:			
Bituminous Coal Underground Mining		a) Total b)	Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
· ·	3	51	ū	51	0	0
12. Contractor Name			13 Co.	ntractor Union	14. Contractor ID N	umher
Puckett Creek Hydroseeding			No.	maddi Gillon	C1419	ubo.
, ,			140		01410	
15. Contractor Address						
a) City	b) County		c) State	d) Zip (
Middlesboro			KY	4096	55	
Number of Contractor Employ	rees					
a) Total	Total b) Underground			d) Mill/Prep Plant	e) Other	
3		3				
17. Number of Persons in Mine at	Time of Accident	18. Number of Persons Ur	accounted for			
a) Mine Employees b) Contractor Employees		a) Mine Employees	b) Contra	ctor Employees		
25	3	0	0			
19. Accident Location					20. Mining Height	
03 - Open Pit					1 Feet 9 Inch	ies
21. Nonfatal Injuries	22. Fatal Injuries				'	
•						
0						

23. Victims Information

Douglas Slushe	er						
a) First Name Douglas	a) MI	a) Last Name Slusher	b) Age 48	, .	ar Job Title seeder operator	 d) Activity at Time of Accident preparing to hydro-seed. 	Employee Contractor Employee
24. Mining Expe a) Total Expe 8 Years 0 V	rience	, ,	erience at t ars 0 Week		c) Experience 8 Years 0 W	at the Activity at the Time of the Accident eeks 0 Days	d) Experience with Contractor 8 Years 0 Weeks 0 Days
25. Autopsy Pe Yes	rformed		L ocation rt, Kentuck	y			

26. Mine Telephone No.

(606) 312-9467

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

A contractor changed the nozzle on a hydro-seeder and then accidentally engaged the hydro-seeder's clutch while the nozzle was pointing towards him. The material being forced through the nozzle struck the victim. This caused the victim to fall backwards striking his neck on the hydro-seeder handrail.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Not listed Finn			29. Model 2500 Hydro-seeder		
30. District			32. Field Office	33. Event Number	
C0700 - Barbourville District			C0701 - Barbourville KY Field Office	4459924	
34. Accident Investigator					
First Name	MI	Last Name			
Dannie	W	Lewis			
35. MSHA Person Notified					
First Name	MI	Last Name	Date/Time Notified		
Crystal	D	Yother	10/09/2020 12:28 PM		
36. Type of Report	37. Name of I	Preparer			
Amended	Full Name	Э	Date Prepared		
	Dannie W	Lewis	10/12/2020		

38. Reason for Amendment

Corrected Contractor ID once operator obtained for this service. Updated employee numbers based on new information gathered. Revised Accident Classification to reflect "Machinery". Updated Victim Information for Time at this Activity based on new information gathered.