

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 09/24/2020

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 09/16/2020 10:25 AM	4. Date/Time of Death 09/16/2020 10:30 AM	5. Fatal Case No FAI-4313135-1
6. Mine Information				
a) Mining Company Name: Clayton Sand Company		b) Mine Name: Woodland Plant		
c) Parent of Mining Company: William Clayton et al				
7. Mine Location Information			8. Mine ID Number 28-00715	9. Union Yes
a) City Neptune	b) County Burlington	c) State NJ		
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.		11. Number of Employees		
		a) Total 9	b) Underground 0	c) Open Pit/Quarry 0
			d) Mill/Prep Plant 0	e) Other 9
12. Contractor Name BYM Trucking LLC			13. Contractor Union No	14. Contractor ID Number C1366
15. Contractor Address				
a) City Burlington	b) County	c) State NJ	d) Zip Code 08016	
16. Number of Contractor Employees				
a) Total 30		b) Underground 0		c) Open Pit/Quarry 0
		d) Mill/Prep Plant 0		e) Other 30
17. Number of Persons in Mine at Time of Accident			18. Number of Persons Unaccounted for	
a) Mine Employees 9		b) Contractor Employees 3		
		a) Mine Employees 0		b) Contractor Employees 0
19. Accident Location 06 - Dredge Mining				20. Mining Height 0 Feet 0 Inches
21. Nonfatal Injuries	22. Fatal Injuries 1			

23. Victims Information

Mehmet Bayram						
a) First Name Mehmet	a) MI	a) Last Name Bayram	b) Age 47	c) Regular Job Title Truck Driver	d) Activity at Time of Accident Truck Driver	Employee Contractor Employee
24. Mining Experience						
a) Total Experience 20 Years 0 Weeks 0 Days		b) Experience at the Mine 3 Years 0 Weeks 0 Days		c) Experience at the Activity at the Time of the Accident 3 Years 0 Weeks 0 Days		d) Experience with Contractor 3 Years 0 Weeks 0 Days
25. Autopsy Performed						
Yes		If Yes, Location Burlington County Medical Examiner				

26. Mine Telephone No.

(609) 726-1200

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

A customer truck driver was run over by his dump truck while he was underneath the truck attempting to adjust the brakes. At the time of the accident, the parking brake was not set and the transmission was in drive with the engine running.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Kenworth		29. Model T880		
30. District C0200 - Mt. Pleasant District		32. Field Office C0208 - Frackville PA Field Office		33. Event Number 4313135
34. Accident Investigator				
First Name Peter	MI B	Last Name Betz		
35. MSHA Person Notified				
First Name Kevin	MI	Last Name Abel	Date/Time Notified 09/16/2020 11:01 AM	
36. Type of Report Initial	37. Name of Preparer		Date Prepared	
	Full Name Thomas J Yencho		09/17/2020	

38. Reason for Amendment