## -

2. Accident Classification

Slip or Fall of Person

a) City

a) City

Brookwood

Preliminary Report of Accident

b) County

a) Total

18

b) Mine Name

11. Number of Mine

**Employees:** 

Johnson Mine

Jefferson

U.S. Department of Labor Mine Safety and Health Administration

10/05/2015 08:11 AM

d) Mill/Prep Plant

0

4. Date/Time of Death

c) Parent of Mining Company

01-03375

Randall E Crawford

8. Mine ID Number:

c) State

c) Open Pit/Quarry

13. Union

18

16 Normhan af Contra			-) T-4-1		TT J		-) 0	D:4/O			1) M:11/D Dl	-)	041		
16. Number of Contrac	torEr	nployees:	a) Total	D)	Underg	rouna	6)0	pen Pit/Quarry			l) Mill/Prep Plant	e)	Other		
17. Number of Persons	in Mi	ne at Time	of Accident:				18. Numb	er of Persons U	naccoun	ted Fo	r:				
a) Mine Employees: 18			b) Contractor Employees:			0	a) Mine Employees: 0			0	b) Contractor Employees:			0	
19) Location of Accide 01-Underground	nt		X 03-Open Pit		07-	Advance	Mining	30-Mill/P	rep Pla	nt	Other (specify)	2	0. Mini Feet	ing Heigh Inches	
02-Surface at Underground			06-Dredge Mi	ning	08-	Retreat <b>M</b>	lining	99-Office Facility					2	1	
21. Nonfatal Injuries:		0	22. Fatal Injuries:	1											
23. Victim Information :			a) Name		b) Age										
			Bobby Wimberly				58								
c) Regular Job Title:			d) Activity at Time of Accident:							X Mine Employee					
Bulldozer (	Opera	tor					Bulldoze	er Operator					-	-	
24. Experience : Ye	ears W	eeks Days		Years Wee	eks Days			Years W	eeks Da	iys		Years Weeks Days			
a) Total:	10	9 1	b) at the mine:	79	91	c) at a	ctivity (23d)	) 7	9	1	d) with Contractor	0	0	0	
25. Autopsy Performed: If Yes,			Location						20	6. Min	e Telephone No.: (205) 361-7712				
27. Description of Acci	dent (i	nclude equ	ipment involved, the o	xact locat	ion in th	e mine, ar	nd status of 1	escue and recov	very ope	ration	s):				

3. Date/Time of Accident

c) State

AL

0

b) Underground

b) County

09/26/2015 05:45 AM

On September 26, 2015 at approximately 5:45 am, a nonfatal injury occurred at this mine site. The mine foreman shuttled the equipment operators to their designated working areas. The C/N 105 Komatsu D375A bulldozer did not arrive at the work site. The mine foreman traveled back to the bulldozer and observed the bulldozer stationary. When the foreman got closer to the bulldozer, he found the bulldozer operator lying on the ground. First aid was started immediately by mine personnel. Mine personnel continued medical treatment until the EMT and paramedics arrived. Then the bulldozer operator was airlifted to the DCH hospital.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufactu	urer: Komat	su	29. Model: D375A					
30. District: C1100 Bi	irmingham	32. Field Offic	32. Field Office: Bessemer AL			33. Event Number: 6492461		
34. Accident Investigator:	8		35. MSHA Person Notified:		Date	Time		
Jarvis F. Westery			Edward M. Boylen		09/26/2015	06:24 AM		
36. Type of Report:		37. Name of Preparer a	e of Preparer and Date Prepared:			Date		
Amended			Jarvis F. Westery		10/05/2015			

38. Reason For Amendment:

The miner never regained consciousness and succumbed to his injuries on October 5, 2015. Changes made to Items 1, 4, 5, 21, 22, 36 and 37.



1. Accident Type:

Fatal Injury

7. Mine Location :

BITUMINOUS

12. Contractor Name:

15. Contractor Address:

6. Mine Information : a) Mining Company Name

Cahaba Resources LLC

10. Primary Mineral Mined:



5. Fatal Case No

10

NO

e) Other

0

9. Union:

14. Contractor ID Number:

d) Zip Code