

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 03/16/2015 05:00 AM		4. Date/Time of Death 03/16/2015 06:47 AM		5. Fatal Case No 4			
6. Mine Information :											
a) Mining Company Name Paramont Coal Company Virginia LLC			b) Mine Name Deep Mine 41			c) Parent of Mining Company Alpha Natural Resources, Inc.					
7. Mine Location :		a) City McClure		b) County Dickenson		c) State VA		8. Mine ID Number: 44-07223		9. Union: NO	
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND			11. Number of Mine Employees:		a) Total 255	b) Underground 229	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other 26	
12. Contractor Name:						13. Union		14. Contractor ID Number:			
15. Contractor Address:			a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total 17	b) Underground 17		c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other		
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:					
a) Mine Employees: 85		b) Contractor Employees: 5		a) Mine Employees: 0		b) Contractor Employees: 0					
19) Location of Accident								20. Mining Height:			
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input checked="" type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility				6	0	
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1								
23. Victim Information :				a) Name David W. Brummitte		b) Age 34					
c) Regular Job Title: Section Foreman			d) Activity at Time of Accident: Section Examinations				<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days			
a) Total:	10	16	0	b) at the mine:	2	0	0	c) at activity (23d)	0	20	0
d) with Contractor	0	0	0								
25. Autopsy Performed: If Yes, Location YES Roanoke, Virginia						26. Mine Telephone No.: (276) 835-9096					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
David Brummitte, Section Foreman, was performing examination duties on the 003 MMU pillar section in the crosscut between No. 3 and No. 4 entries 90 feet inby spad 4450. Mr. Brummitte was working alone when he was struck by a rib roll and pinned against a Joy 10 SC shuttle car. Mr. Brummitte received blunt force injuries to his right side and upper body resulting in his death.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co)			29. Model: 10 SC shuttle car		
30. District: C0500 Norton		32. Field Office: Norton VA			33. Event Number: 4417812
34. Accident Investigator: Jason D. Hess			35. MSHA Person Notified: Jason D. Lane		Date 03/16/2015
					Time 05:11 A
36. Type of Report: Amended		37. Name of Preparer and Date Prepared Terry R. Sheffield			Date 03/16/2015

38. Reason For Amendment:
David Brummitte was a Paramont Coal employee.