

# SAFETY RECALL

## Certain Fluke 333, 334, 335, 336 and 337 Digital Clamp Meters

Manufactured between January 29, 2008 and February 27, 2009



| Recalled clamp meters                      |                     |                   |
|--|---------------------|-------------------|
| Model Family                               | Starting Serial No. | Ending Serial No. |
| Fluke-337 (All 337 models, including 337A) | 96070000            | 98890607          |
| Fluke-336 (All 336 models, including 336A) | 96220000            | 98900400          |
| Fluke-335 (All 335 models, including 335A) | 97010000            | 98860104          |
| Fluke-334 (All 334 models, including 334A) | 97010000            | 98870101          |
| Fluke-333 (All 333 models, including 333A) | 97010000            | 98880240          |

*Note: Serial numbers that begin with "S" or are followed by "R" are NOT included in the recall.*

### **Potential short circuit in clamp meter may lead to inaccurate or no voltage reading on circuit energized with hazardous voltage.**

Customers should stop using these clamp meters immediately and contact Fluke for instructions to return these models and receive a free replacement unit. Contact Fluke at:

- [www.fluke.com/33Xrecall](http://www.fluke.com/33Xrecall)
- 1-888-98-FLUKE (35853), 7 a.m. to 4 p.m. Pacific Time Monday–Friday