

Preventing Falls from Height

In the last ten years, 22 miners and contractors have been fatally injured and over 1,000 have been disabled or lost time from work in fall-from-height accidents.

Fall from height accidents result in over 100 fatal and serious injuries every year. Prevent these injuries by providing walkways and platforms with handrails that provide safe access, and by using adequate fall protection.



Above: Unsafe - No place to attach workers' lanyards

Near right: Safe - Good use of retractable lanyard

Far right: Safe - Dual lanyards used for tie-off when working and moving at height



Left: Unsafe - Mechanic with no fall protection



Best Practices

- **Reduce hazards.** Design work areas and develop job tasks to minimize fall hazards.
- **Have a program.** Establish an effective fall prevention and protection program. Provide task and site-specific hazard training that prohibits working at unprotected locations.
- **Provide fall protection** to each miner who may work at an elevated height, or a location unprotected by handrails. Ensure their use.
- **Provide secure anchor points.**
- **Provide mobile or stationary platforms or scaffolding** at locations and on work projects where there is a risk of falling.
- **Provide safe truck tarping and bulk truck hatch access facilities.**

Report accidents and hazardous conditions: 1-800-746-1553

msha.gov | askmsa@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)