

Preliminary Report of Accident



PR001 10/22/2021

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 10/19/2021 2:15 PM	4. Date/Time of Death 10/19/2021 3:50 PM	5. Fatal Case No FAI 6282349-01
---	---	---	--	---

6. Mine Information				
a) Mining Company Name:		CCU Coal and Construction LLC		
b) Mine Name:		Buckingham Mine		
c) Parent of Mining Company:		Charles C Ungurean		

7. Mine Location Information			8. Mine ID Number	9. Union
a) City GLOUSTER	b) County Perry	c) State OH	33-04526	No

10. Primary Mineral Mined Bituminous Coal Underground Mining	11. Number of Employees			
	a) Total 10	b) Underground 0	c) Open Pit/Quarry 0	d) Mill/Prep Plant 0
				e) Other 10

12. Contractor Name	13. Contractor Union	14. Contractor ID Number

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees 10	b) Contractor Employees	a) Mine Employees 0	b) Contractor Employees

19. Accident Location 02 - Surface at Underground	20. Mining Height 0 Feet 0 Inches
---	---

21. Nonfatal Injuries 0	22. Fatal Injuries 1
-----------------------------------	--------------------------------

23. Victims Information						
David P Steen						
a) First Name David	a) MI P	a) Last Name Steen	b) Age 58	c) Regular Job Title Mechanic	d) Activity at Time of Accident Performing work on rock truck	Employee Mine Employee
24. Mining Experience						
a) Total Experience 17 Years 22 Weeks 2 Days		b) Experience at the Mine 17 Years 22 Weeks 2 Days		c) Experience at the Activity at the Time of the Accident 0 Years 26 Weeks 4 Days		d) Experience with Contractor Years Weeks Days
25. Autopsy Performed						
Yes		If Yes, Location Columbus Ohio				

26. Mine Telephone No. (740) 610-3712

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)
A mechanic was trying to remove a pin from the bed leveling cylinder on an articulating haul truck, when the bed of the truck fell on the victim.
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Caterpillar	29. Model D400E Articulated Truck
--	---

30. District C0300 - Morgantown District	32. Field Office C0303 - Bridgeport WV Field Office	33. Event Number 6282349
--	---	------------------------------------

34. Accident Investigator		
First Name Jeremy	MI T	Last Name Doshen

35. MSHA Person Notified			
First Name Micheal	MI	Last Name Stark	Date/Time Notified 10/19/2021 2:44 PM

36. Type of Report Initial	37. Name of Preparer Full Name Jeremy T Doshen	Date Prepared 10/19/2021
--------------------------------------	---	------------------------------------

38. Reason for Amendment