

Fatality Alert

MINE FATALITY – On March 1, 2023, a miner died when the bulldozer he was operating went over an embankment, ejecting him from the operator’s cab.



Best Practices

Operators should train miners to:

- Wear a seat belt while operating mobile equipment.
- Examine ground conditions before beginning work in an area and as ground conditions warrant during the work shift.
- Operate equipment safely, and to identify and report hazards.
- Be aware of their position relative to edges of roadways and benches.

This is the tenth fatality reported in 2023, and the fourth classified as “Machinery.”

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)