

Fatality Alert

MINE FATALITY – On November 13, 2023, a rotating drill steel of a roof bolting machine entangled a miner, causing fatal injuries.



Best Practices

- Always follow manufacturer recommendations when conducting maintenance on equipment, including:
 - Turn off or de-energize the machine.
 - Secure the equipment against hazardous motion.
- Never touch or hold the drill steel, wrench, or bolt while it is rotating.
- Do not wear loose-fitting or bulky clothing when working around any machinery with rotating parts.

This is the 36th fatality reported in 2023, and the 14th classified as “Machinery.”

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)