



## **Fatality Alert**

MINE FATALITY – On September 8, 2023, a miner died after entering a hopper to clear an obstruction. A front-end loader dumped two loads of crushed limestone into the hopper with the miner inside.



## **Best Practices**

- Install barricades to prevent mobile equipment access to bins and hoppers when miners are working in them.
- Establish and train miners on procedures for safely clearing bins and hoppers.
- Lock-out and tag-out the supply and discharge equipment before entering bins and hoppers.
- Wear a safety belt or harness equipped with a lifeline in a confined space.
- Equip bins and hoppers with vibrating shakers or air cannons to prevent material blockages.

This is the 31<sup>st</sup> fatality reported in 2023, and the seventh classified as "Powered Haulage."

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

msha.gov | askmsha@dol.gov | @MSHA\_DOL