

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 12/18/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 17 - Machinery		3. Date/Time of Accident 12/14/2023 2:28 PM		4. Date/Time of Death 12/14/2023 4:28 PM		5. Fatal Case No FAI-6943854-1	
6. Mine Information									
a) Mining Company Name:		Staker & Parson Companies							
b) Mine Name:		Beck Street							
c) Parent of Mining Company:		CRH PLC							
7. Mine Location Information					8. Mine ID Number		9. Union		
a) City Draper		b) County Salt Lake		c) State UT	42-01452		No		
10. Primary Mineral Mined Construction Sand & Gravel Mining, N.E.C.					11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant
					a) Total 42	b) Underground	42		0
12. Contractor Name B.E.S.T. Electric, Inc.					13. Contractor Union			14. Contractor ID Number C0262	
15. Contractor Address					d) Zip Code				
a) City SOUTH JORDAN		b) County Salt Lake		c) State UT	84095				
16. Number of Contractor Employees					c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
a) Total 13		b) Underground		11				2	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for				
a) Mine Employees 22		b) Contractor Employees 6			a) Mine Employees 0		b) Contractor Employees 0		
19. Accident Location 03 - Open Pit							20. Mining Height Feet Inches		
21. Nonfatal Injuries				22. Fatal Injuries 1					
23. Victims Information									
Jay S Swaffar									
a) First Name Jay		a) MI S	a) Last Name Swaffar		b) Age 56	c) Regular Job Title Shop Assistant		d) Activity at Time of Accident Delivering Parts	Employee Contractor Employee
24. Mining Experience									
a) Total Experience 0 Years 0 Weeks 0 Days		b) Experience at the Mine 0 Years 0 Weeks 1 Days			c) Experience at the Activity at the Time of the Accident 0 Years 6 Weeks 2 Days			d) Experience with Contractor 0 Years 6 Weeks 2 Days	
25. Autopsy Performed Yes				If Yes, Location Draper, UT					
26. Mine Telephone No. (801) 298-7500									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The victim was delivering electrical parts to the mine site when he was struck by a telehandler that tipped over. The telehandler was being used to pull electrical cable at the time of the accident. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Caterpillar					29. Model TL1255D				
30. District M6000 - Denver District					32. Field Office M6851 - Salt Lake City UT Field Office			33. Event Number 6943854	
34. Accident Investigator									
First Name Mark		MI Earl	Last Name Phillips						
35. MSHA Person Notified									
First Name Peter		MI A	Last Name Del Duca		Date/Time Notified 12/14/2023 3:12 PM				
36. Type of Report Initial			37. Name of Preparer Full Name Peter DelDuca			Date Prepared 12/15/2023			
38. Reason for Amendment									