

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 06/26/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 17 - Machinery		3. Date/Time of Accident 06/22/2023 2:31 PM		4. Date/Time of Death 06/22/2023 2:54 PM		5. Fatal Case No FAI-6878447-1																																						
6. Mine Information																																														
a) Mining Company Name:		CalMat Co																																												
b) Mine Name:		Chula Vista Quarry																																												
c) Parent of Mining Company:		Vulcan Materials Company																																												
7. Mine Location Information				8. Mine ID Number			9. Union																																							
a) City Chula Vista		b) County San Diego		c) State CA	04-04080		No																																							
10. Primary Mineral Mined Crushed & Broken Stone Mining, N.E.C.				11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other																																				
				a) Total 37		11		17		9																																				
12. Contractor Name LB3 Enterprises, Inc						13. Contractor Union No		14. Contractor ID Number Z740																																						
15. Contractor Address				b) County		c) State		d) Zip Code																																						
a) City Lakeside				CA		92040																																								
16. Number of Contractor Employees																																														
a) Total 2		b) Underground			c) Open Pit/Quarry 2		d) Mill/Prep Plant		e) Other																																					
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for																																									
a) Mine Employees 31		b) Contractor Employees 2			a) Mine Employees 0		b) Contractor Employees 0																																							
19. Accident Location 03 - Open Pit								20. Mining Height Feet Inches																																						
21. Nonfatal Injuries 0		22. Fatal Injuries 1																																												
23. Victims Information																																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">a) First Name John</td> <td style="width: 5%;">a) MI C</td> <td style="width: 20%;">a) Last Name Hatfield</td> <td style="width: 5%;">b) Age 60</td> <td style="width: 15%;">c) Regular Job Title Equipment Operator</td> <td style="width: 20%;">d) Activity at Time of Accident Operating Bulldozer</td> <td style="width: 20%;">Employee Contractor Employee</td> </tr> <tr> <td colspan="10">24. Mining Experience</td> </tr> <tr> <td colspan="2">a) Total Experience 27 Years 0 Weeks 0 Days</td> <td colspan="3">b) Experience at the Mine 2 Years 8 Weeks 0 Days</td> <td colspan="2">c) Experience at the Activity at the Time of the Accident 27 Years 0 Weeks 0 Days</td> <td colspan="3">d) Experience with Contractor 27 Years 0 Weeks 0 Days</td> </tr> <tr> <td colspan="2">25. Autopsy Performed Yes</td> <td colspan="8">If Yes, Location San Diego Coroner</td> </tr> </table>										a) First Name John	a) MI C	a) Last Name Hatfield	b) Age 60	c) Regular Job Title Equipment Operator	d) Activity at Time of Accident Operating Bulldozer	Employee Contractor Employee	24. Mining Experience										a) Total Experience 27 Years 0 Weeks 0 Days		b) Experience at the Mine 2 Years 8 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 27 Years 0 Weeks 0 Days		d) Experience with Contractor 27 Years 0 Weeks 0 Days			25. Autopsy Performed Yes		If Yes, Location San Diego Coroner							
a) First Name John	a) MI C	a) Last Name Hatfield	b) Age 60	c) Regular Job Title Equipment Operator	d) Activity at Time of Accident Operating Bulldozer	Employee Contractor Employee																																								
24. Mining Experience																																														
a) Total Experience 27 Years 0 Weeks 0 Days		b) Experience at the Mine 2 Years 8 Weeks 0 Days			c) Experience at the Activity at the Time of the Accident 27 Years 0 Weeks 0 Days		d) Experience with Contractor 27 Years 0 Weeks 0 Days																																							
25. Autopsy Performed Yes		If Yes, Location San Diego Coroner																																												
26. Mine Telephone No. (619) 591-4717																																														
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor employee died after the bulldozer he was operating backed over the edge of a highwall. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>																																														
28. Equipment Manufacturer Caterpillar					29. Model D9 T																																									
30. District M7000 - Vacaville District					32. Field Office M7831 - San Bernardino CA Field Office			33. Event Number 6878447																																						
34. Accident Investigator			MI			Last Name																																								
First Name Kenneth					Pettus																																									
35. MSHA Person Notified			MI			Date/Time Notified																																								
First Name Leanne					06/22/2023 3:46 PM																																									
36. Type of Report Initial		37. Name of Preparer			Date Prepared																																									
		Full Name Kenneth Pettus			06/23/2023																																									
38. Reason for Amendment																																														