

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 05/19/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 05 - Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 05/16/2023 11:15 PM		4. Date/Time of Death 05/16/2023 11:15 PM		5. Fatal Case No FAI-6934629-1		
6. Mine Information										
a) Mining Company Name:		NACG Texas, Inc.								
b) Mine Name:		San Miguel Lignite Mine								
c) Parent of Mining Company:		North American Construction Group, LTD								
7. Mine Location Information						8. Mine ID Number		9. Union		
a) City CHRISTINE		b) County Atascosa		c) State TX		41-02840		No		
10. Primary Mineral Mined Lignite				11. Number of Employees			d) Mill/Prep Plant		e) Other	
				a) Total 286	b) Underground	c) Open Pit/Quarry 279	0		7	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number		
15. Contractor Address										
a) City		b) County			c) State		d) Zip Code			
16. Number of Contractor Employees										
a) Total		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for						
a) Mine Employees 45		b) Contractor Employees		a) Mine Employees		b) Contractor Employees				
19. Accident Location 03 - Open Pit								20. Mining Height 130 Feet 0 Inches		
21. Nonfatal Injuries		22. Fatal Injuries 1								
23. Victims Information										
Able Calvillo										
a) First Name	a) MI	a) Last Name		b) Age	c) Regular Job Title			d) Activity at Time of Accident		Employee
Able		Calvillo		65	Heavy Equipment Operator			Moving material from road		Mine Employee
24. Mining Experience										
a) Total Experience		b) Experience at the Mine			c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor		
10 Years 15 Weeks 1 Days		10 Years 15 Weeks 1 Days			10 Years 15 Weeks 1 Days			Years Weeks Days		
25. Autopsy Performed		If Yes, Location								
Yes		Jourdanon, TX								
26. Mine Telephone No. (830) 784-3545										
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner died when the material from a spoil pile slid, engulfing the bulldozer he was operating and causing it to roll over onto its side. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
28. Equipment Manufacturer Caterpillar				29. Model D5K Bulldozer						
30. District M5000 - Dallas District				32. Field Office M5611 - San Antonio TX Field Office				33. Event Number 6934629		
34. Accident Investigator										
First Name		MI		Last Name						
Armando				Moreno						
35. MSHA Person Notified										
First Name		MI		Last Name			Date/Time Notified			
Armando				Moreno			05/17/2023 4:31 AM			
36. Type of Report Initial		37. Name of Preparer			Date Prepared					
		Full Name Armando Moreno			05/17/2023					
38. Reason for Amendment										