

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 05/24/2023

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 12 - Powered Haulage		<b>3. Date/Time of Accident</b> 05/22/2023 11:15 AM		<b>4. Date/Time of Death</b> 05/22/2023 2:18 PM		<b>5. Fatal Case No</b> FAI--7041240-1	
<b>6. Mine Information</b>									
a) Mining Company Name:		Central Stone Company							
b) Mine Name:		HUNTINGTON PLANT CS01							
c) Parent of Mining Company:									
<b>7. Mine Location Information</b>			<b>8. Mine ID Number</b>			<b>9. Union</b>			
a) City Davenport		b) County Ralls		c) State MO		23-00079			No
<b>10. Primary Mineral Mined</b> Crushed & Broken Limestone Mining, N.E.C.					<b>11. Number of Employees</b>		<b>c) Open Pit/Quarry</b>		<b>d) Mill/Prep Plant</b>
					a) Total 20		20		e) Other
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>	
<b>15. Contractor Address</b>									
a) City		b) County			c) State		d) Zip Code		
<b>16. Number of Contractor Employees</b>									
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant	
								e) Other	
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>				
a) Mine Employees 15		b) Contractor Employees			a) Mine Employees		b) Contractor Employees		
<b>19. Accident Location</b> 03 - Open Pit								<b>20. Mining Height</b> 52 Feet Inches	
<b>21. Nonfatal Injuries</b>		<b>22. Fatal Injuries</b> 1							
<b>23. Victims Information</b>									
<b>Darrell E Huff</b>									
a) First Name Darrell		a) MI E	a) Last Name Huff		b) Age 70	c) Regular Job Title Stock Pile Driver		d) Activity at Time of Accident Stock Pile Driver	Employee Mine Employee
<b>24. Mining Experience</b>									
a) Total Experience 49 Years 39 Weeks 2 Days		b) Experience at the Mine 49 Years 39 Weeks 2 Days			c) Experience at the Activity at the Time of the Accident 12 Years 39 Weeks 2 Days			d) Experience with Contractor 12 Years 39 Weeks 2 Days	
<b>25. Autopsy Performed</b> No			If Yes, Location						
<b>26. Mine Telephone No.</b> (573) 735-4525									
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner died when the haul truck he was operating backed through a berm on top of a stockpile, overturned, and landed on the roof of the cab.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
<b>28. Equipment Manufacturer</b> Komatsu					<b>29. Model</b> 605 HD				
<b>30. District</b> C1000 - Madisonville District					<b>32. Field Office</b> C1004 - Rolla MO Field Office			<b>33. Event Number</b> 7041240	
<b>34. Accident Investigator</b>									
First Name Nicholas		MI P	Last Name Dunne						
<b>35. MSHA Person Notified</b>									
First Name Hubert		MI G	Last Name Wright		Date/Time Notified 05/22/2023 12:27 PM				
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b> Full Name Curtis R Hardison			Date Prepared 05/23/2023				
<b>38. Reason for Amendment</b>									