


Fatality Alert

MINE FATALITY – On November 17, 2023, a miner died when the leg of a rock saw stand that he was assisting to unload, shifted and struck him.



Best Practices

- Review safe procedures with all miners involved prior to conducting a non-routine task.
- Use proper rigging and lifting procedures when moving machine parts.
- Load and unload materials on smooth, level surfaces to ensure the material does not shift or fall over.
- Ensure miners are positioned in a safe location and away from potential hazards when moving or positioning equipment.

This is the 37th fatality reported in 2023, and the first classified as “Handling Material.”

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)