

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 01/05/2024

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 01/02/2024 4:46 AM		4. Date/Time of Death 01/02/2024 4:46 AM		5. Fatal Case No FAI-6938605-1	
6. Mine Information									
a) Mining Company Name:		Frontera Materials Inc							
b) Mine Name:		MOBILE CRUSHER #3 FRONTERA MATERIALS							
c) Parent of Mining Company:		Edwin E Forshage III et al							
7. Mine Location Information					8. Mine ID Number		9. Union		
a) City ELSA		b) County Hidalgo		c) State TX	41-04292		No		
10. Primary Mineral Mined Crushed & Broken Stone Mining, N.E.C.					11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant
					a) Total 32	b) Underground 0	32		0
12. Contractor Name					13. Contractor Union			14. Contractor ID Number	
15. Contractor Address									
a) City		b) County			c) State		d) Zip Code		
16. Number of Contractor Employees									
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for				
a) Mine Employees 2		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees		
19. Accident Location 00 - Other Overload Dump Area								20. Mining Height Feet Inches	
21. Nonfatal Injuries				22. Fatal Injuries 1					
23. Victims Information									
[Redacted]									
a) First Name Luis		a) MI	a) Last Name Rivera		b) Age 46	c) Regular Job Title Truck Driver		d) Activity at Time of Accident Operating Truck	Employee Other Employee
24. Mining Experience		b) Experience at the Mine			c) Experience at the Activity at the Time of the Accident			d) Experience with Contractor	
a) Total Experience Years 16 Weeks Days		Years Weeks 1 Days			Years 16 Weeks Days			Years Weeks Days	
25. Autopsy Performed Yes			If Yes, Location Hidalgo County						
26. Mine Telephone No. (956) 422-0005									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) An over-the-road truck driver was killed when the truck's trailer fell on the cab of his truck. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Kenworth					29. Model W900				
30. District M5000 - Dallas District					32. Field Office M5611 - San Antonio TX Field Office			33. Event Number 6938605	
34. Accident Investigator									
First Name Michael		MI		Last Name Tefertiller					
35. MSHA Person Notified									
First Name John		MI S		Last Name Powers			Date/Time Notified 01/02/2024 5:22 AM		
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name Jason Hoermann			01/02/2024				
38. Reason for Amendment									