

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 10/16/2010 08:11 AM		4. Date/Time of Death 10/16/2010 09:18 AM		5. Fatal Case No 18		
6. Mine Information :										
a) Mining Company Name N R Hamm Quarry Inc			b) Mine Name Plant #80013			c) Parent of Mining Company N R Hamm				
7. Mine Location :		a) City Perry		b) County Jefferson		c) State KS		8. Mine ID Number: 14-01609		9. Union: YES
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M		11. Number of Mine Employees:		a) Total 8	b) Underground 0	c) Open Pit/Quarry 4		d) Mill/Prep Plant 4	e) Other 0	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 8		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet    Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name William W. Oaks				b) Age 52						
c) Regular Job Title: Haul Truck Driver				d) Activity at Time of Accident: Cleaning tail pulley						
<input checked="" type="checkbox"/> Mine Employee										
24. Experience :										
Years		Weeks		Days		Years		Weeks		Days
a) Total: 5		12		b) at the mine: 5		12		c) at activity (23d): 5		12
d) with Contractor										
25. Autopsy Performed: If Yes, Location YES Topeka, KS						26. Mine Telephone No.: (785) 597-5111				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was cleaning hardened material on a belt conveyor tail pulley. He was using an air-powered hammer/chisel and was positioned on top of the bottom belt facing the tail pulley. The belt conveyor was energized entangling him in the tail pulley.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: N/A			29. Model: N/A		
30. District: M6000 Rocky Mountain		32. Field Office: Topeka KS			33. Event Number: 6520958
34. Accident Investigator: David M. Sinquefield			35. MSHA Person Notified: Dustan Crely		Date    Time 10/16/2010    08:18 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 10/17/2010
38. Reason For Amendment:					