

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 02/12/2011 07:03 AM		4. Date/Time of Death 02/12/2011 07:35 AM		5. Fatal Case No 1					
6. Mine Information :													
a) Mining Company Name C F Industries Inc			b) Mine Name HARDEE PHOSPHATE COMPLEX			c) Parent of Mining Company Stephen R Wilson							
7. Mine Location :		a) City Bowling Green		b) County Hardee		c) State FL		8. Mine ID Number: 08-00903		9. Union: NO			
10. Primary Mineral Mined: PHOSPHATE ROCK MINING		11. Number of Mine Employees:		a) Total 163	b) Underground	c) Open Pit/Quarry 102	d) Mill/Prep Plant 61	e) Other					
12. Contractor Name: McDonald Construction						13. Union NO		14. Contractor ID Number: BA3					
15. Contractor Address:		a) City Lakeland		b) County Polk		c) State FL		d) Zip Code 33801					
16. Number of Contractor Employees:		a) Total 353		b) Underground		c) Open Pit/Quarry 353		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:								
a) Mine Employees: 33		b) Contractor Employees: 170			a) Mine Employees: 0		b) Contractor Employees: 0						
19) Location of Accident									20. Mining Height:				
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches			
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility										
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1											
23. Victim Information :				a) Name Jose A. Soto		b) Age 41							
c) Regular Job Title: Grader Operator			d) Activity at Time of Accident: Checking equipment <input checked="" type="checkbox"/> Contractor Employee										
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days					
a) Total:		15		b) at the mine:		24		c) at activity (23d)		15	d) with Contractor		15
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (863) 375-4321							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was struck by a road grader when it backed up. The accident occurred in the staging area where the victim and other coworkers were checking their equipment for the shift. There were 15 road graders and 4 haul trucks in the area.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: CAT 1544			29. Model: 12 H		
30. District: M3000 Southeastern		32. Field Office: Bartow FL			33. Event Number: 0913416
34. Accident Investigator: Billy Randolph		35. MSHA Person Notified: Doniece Schlick		Date 02/12/2011	Time 07:05 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 02/14/2011
38. Reason For Amendment:					