

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Roof or Back		3. Date/Time of Accident 09/13/2012 03:30 PM		4. Date/Time of Death 09/13/2012 03:30 PM		5. Fatal Case No 15			
6. Mine Information :											
a) Mining Company Name Consolidation Coal Company			b) Mine Name Blacksville No 2			c) Parent of Mining Company CONSOL Energy Inc					
7. Mine Location :		a) City Wana		b) County Monongalia		c) State WV		8. Mine ID Number: 46-01968		9. Union: YES	
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND		11. Number of Mine Employees:		a) Total 490	b) Underground 427	c) Open Pit/Quarry 0		d) Mill/Prep Plant 49	e) Other 14		
12. Contractor Name:						13. Union		14. Contractor ID Number:			
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code			
16. Number of Contractor Employees:											
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:						
a) Mine Employees: 106		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident								20. Mining Height:			
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches		
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility					6	6		
21. Nonfatal Injuries:		22. Fatal Injuries: 1									
23. Victim Information :											
a) Name William E. Mock					b) Age 61						
c) Regular Job Title: General Inside Laborer				d) Activity at Time of Accident: General Inside Laborer				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :											
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days		
a) Total:	38 2 3		b) at the mine:	3 25 6		c) at activity (23d)	3 25 6		d) with Contractor	0 0 0	
25. Autopsy Performed: If Yes, Location YES Carow College, Pittsburgh, PA								26. Mine Telephone No.: (724) 451-3233			

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Thursday, September 13, 2012, at approximately 3:30 p.m., William E. Mock, a 61 year old general inside laborer was fatally injured when he and another employee were attempting to increase the vertical clearance between the track rail and the trolley wire at 116 block on the Main North Track Haulage. The victim and another employee were cutting wooden roof planks from the mine roof, when a section of roof, above the plank fell striking the victim, pinning him to the mine floor.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: C0300 Morgantown		32. Field Office: Morgantown WV				33. Event Number: 6264834	
34. Accident Investigator: Jan B. Lyall			35. MSHA Person Notified: Ronald Tulanowski_DataTrac			Date 09/13/2012	Time 04:56 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared LS for Bob E. Cornett, DM				Date 09/14/2012	
38. Reason For Amendment:							