

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Slip or Fall of Person		3. Date/Time of Accident 02/22/2012 08:00 PM		4. Date/Time of Death 02/26/2012 06:30 PM		5. Fatal Case No 3		
6. Mine Information :										
a) Mining Company Name White Rock Quarries			b) Mine Name WHITE ROCK QUARRIES			c) Parent of Mining Company Vecellio Group Inc				
7. Mine Location :		a) City Hialeah		b) County Dade		c) State FL		8. Mine ID Number: 08-01058		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 102	b) Underground 102	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 25		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries:			22. Fatal Injuries:			1				
23. Victim Information :										
a) Name Humberto Guerra				b) Age 46						
c) Regular Job Title: Plant Mechanic				d) Activity at Time of Accident: Working on snub pulley				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years		Weeks		Days		Years		Weeks		Days
a) Total: 7		b) at the mine: 7		c) at activity (23d): 7		d) with Contractor				
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (305) 822-5322				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

Guerra and a coworker were replacing a snub pulley on an elevated radial stacker conveyor. Guerra was standing on a walkway on one side of the conveyor and his coworker was standing on a walkway on the other side of the conveyor. They were attempting to maneuver the pulley into position to bolt it in place when the victim fell 16 feet to the ground below. He was hospitalized and died on February 26, 2012.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M3000 Southeastern		32. Field Office: Bartow FL			33. Event Number: 0916826		
34. Accident Investigator: Jeffrey Phillips			35. MSHA Person Notified: Doniece Schlick		Date 02/22/2012		Time 08:28 P
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 02/28/2012		
38. Reason For Amendment: Item #10							