

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 05/23/2012 12:15 PM		4. Date/Time of Death 05/23/2012 06:50 PM		5. Fatal Case No 7		
6. Mine Information :										
a) Mining Company Name Meridian Aggregates Company, A Limited Par			b) Mine Name Broken Bow Sand & Gravel			c) Parent of Mining Company Martin Marietta Materials Inc				
7. Mine Location :		a) City Eagletown		b) County Mccurtain		c) State OK		8. Mine ID Number: 34-00460		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 15		b) Underground 14		c) Open Pit/Quarry 1	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State		d) Zip Code			
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 12		b) Contractor Employees:			a) Mine Employees:		b) Contractor Employees:			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries:		22. Fatal Injuries:		1						
23. Victim Information :										
a) Name John P. Scott				b) Age 36						
c) Regular Job Title: Foreman				d) Activity at Time of Accident: Operating an excavator				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:	9	20	3	b) at the mine:	9	20	3	c) at activity (23d)	5 8 0	d) with Contractor
25. Autopsy Performed: If Yes, Location YES						26. Mine Telephone No.: (580) 835-7311				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating an excavator between two small ponds when the ground beneath the excavator tracks failed and the excavator toppled into one of the ponds.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 330			
30. District: M5000 South Central		32. Field Office: Norman OK			33. Event Number: 6543587	
34. Accident Investigator: Laurence M. Dunlap			35. MSHA Person Notified: Elwood M. Burriss		Date 05/23/2012	Time 12:30 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 05/24/2012	
38. Reason For Amendment:						