

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling Material		3. Date/Time of Accident 08/17/2012 08:20 AM		4. Date/Time of Death 08/17/2012 08:20 AM		5. Fatal Case No 12								
6. Mine Information :																
a) Mining Company Name Tarmac America LLC			b) Mine Name PENNSUCO CEMENT PLANT			c) Parent of Mining Company Titan Cement Company S A										
7. Mine Location :		a) City Medley		b) County Miami-Dade		c) State FL		8. Mine ID Number: 08-00051		9. Union: NO						
10. Primary Mineral Mined: HYDRAULIC CEMENT			11. Number of Mine Employees:		a) Total 130	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant 109	e) Other 21							
12. Contractor Name:						13. Union		14. Contractor ID Number:								
15. Contractor Address:																
a) City		b) County			c) State			d) Zip Code								
16. Number of Contractor Employees:																
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other								
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:										
a) Mine Employees: 74		b) Contractor Employees: 0				a) Mine Employees: 1		b) Contractor Employees:								
19) Location of Accident									20. Mining Height:							
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches							
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility											
21. Nonfatal Injuries:			22. Fatal Injuries: 1													
23. Victim Information :																
a) Name Pierre Mezidor					b) Age 58											
c) Regular Job Title: Cement Equipment Operator						d) Activity at Time of Accident: Measuring material in the silo				<input checked="" type="checkbox"/> Mine Employee						
24. Experience :																
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days							
a) Total:		19	8	0	b) at the mine:		19	8	0	c) at activity (23d)		10	0	0	d) with Contractor	
25. Autopsy Performed: NO						26. Mine Telephone No.: (305) 823-8800										

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was on top of a 200-foot tall silo, measuring the amount of cement in the silo, when the roof of the silo collapsed. Rescuers responded and recovered the victim on September 4, 2012.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:				
30. District: M3000 Southeastern		32. Field Office: Bartow FL			33. Event Number: 0916943			
34. Accident Investigator: Scott Johnson			35. MSHA Person Notified: Shawn Sharp			Date 08/17/2012		Time 08:45 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>				Date 09/04/2012		
38. Reason For Amendment:								