

*B loader Area
Behind wall*

PRE-SHIFT - ONSHIFT

and

DAILY REPORT
STARTED

12-16-9

Company

Mine

SECTION

LOCATION

Post Office

County

State

Finished 11-7-10



Re-order from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, WV 25801
Phone (304) 253-7361

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination _____ 20____ Section or Area Examined _____
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	<i>Void</i>	_____
2. _____		_____
3. _____		_____
4. _____		_____
5. _____		_____
6. _____		_____
7. _____		_____
8. _____		_____
9. _____		_____
10. _____		_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner	_____ Certificate No.	_____ Assistant Foreman	_____ Certificate No.
Countersigned _____ Mine Manager Mine Foreman	_____	_____	_____
_____ Assistant Foreman	_____	_____ Superintendent or Assistant	_____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made.

Date 12-16 Shift 3RD Area or Section Bleeder Area

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-16-9 Section or Area Examined Bleeder Area
 Time of Examination: from 4:00 a.m. or p.m. to 5:30 a.m. or p.m.
 Was this report phoned to outside? yes no
 By whom Kenny Farmer Time 5:35 A.M. P.M.
 Report received by Etzgen (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 72 BK to 125 BK	00.5 CH ₄ OX 20.8	up
2. 88 BK to 124	water in several places	
3. 4 air pumps running in #4 entry	12 & 3 entries	up
4. 100 BK	12" water 2 pumps running air pumps	clean
5. #4 Entry	1 Pump in #3	
6. 123 BK	water is down	
7. #4 Entry	one pump is running setting another pump in it	
8. #1 Entry	Added 3" Pump	Pumps

Air Measurements

Location	CFM	Location	CFM

Remarks: I always clear 00.5% Methane found OX 20.8

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kenny Farmer Certificate No. 32294
 Countersigned Etzgen Mine Foreman Certificate No. 26001
 Assistant Foreman Certificate No. 1477A
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-16-09 Section or Area Examined bleeder Const.
 Time of Examination: from 12:01 a.m. or 1:30 p.m. to 1:30 a.m. or 1:30 p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>72BK - 125BK</u>	<u>water in several places</u>	<u>pumping</u>
2.			
3.	<u>OCH4 - 20.89002</u>	<u>72B 74-88 - 120-125Bk</u>	
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1479-A Certificate No. 26041 [Signature] Assistant Foreman 33238 Certificate No.
 Countersigned [Signature] Mine/Manager Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 12-16 Shift Even Area or Section Bleeder

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.	Took in discharge line to 123 break and extended discharge line to Sump hole pumped to holes dry on 1 entry and pumping in last swage	
2.		
3.		
4.		
5.		
6.		
7.	Hung 2 pumps back up that had fallen	
8.		
9.		
10.		
	Tied several leaks in other discharge lines	

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. 85 Break	2 entry	24 inches	0.6%	11.	
2.	3 entry	40 inches		12.	
3.				13.	
4. 100 Break	4 entry	1 inch	0.6%	14.	
5.				15.	
6.				16.	
7. 123 break	1 entry	12 inches	pumping	17.	
8.	2	20 inches		18.	
9.	3	33 inches	0.6%	19.	
10.	4	40 inches		20.	

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Kyle Anderson 33238 E. Hagan 26044
 Assistant Mine Foreman Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-16 2009 Section or Area Examined Bleeder
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time A.M. 2248 P.M.
 Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>72-125 BLC</u>	<u>Water in various places</u>	<u>pumpings</u>
2. _____	<u>72-74-88-120-125 BLC</u>	_____
3. _____	<u>0% CH4</u>	_____
4. _____	<u>20.802</u>	_____
5. _____	<u>0% CO</u>	_____
6. _____	_____	_____
7. <u>Traveled from 85 to 126 bunk</u>	<u>26 CH4 208</u>	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 33238 Certificate No. _____
 Preshift-Mine Examiner
 Countersigned [Signature] 26041 Certificate No. _____
 Mine Manager Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant
 _____ Certificate No. 1946-A
3024

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-17 20 89 Section or Area Examined Bleedun
 Time of Examination: from 12:30 a.m. to 4:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 88 Bak to 125	water in various places	Pumping
2. 88 Bak #4 - #3	water 24" +	Pumping
3. 100 Bak #4 ; +3	water down	
4. 123 Bak #4	water approx. 24"	Pumping
5. #3	" " 36"	Pumping
6. 125 Bak #1	water is down	
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good per movement in all entries			

Remarks: Highways clean at time of exam
top scaling some old + 2 sections 82 Bak to 86 Bak -
in process of setting sand tracks
Reported return stopping at 84 Bak.

CH₄ - 0% CO - 0% O₂ - 20.8%

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32254 Certificate No.
 Countersigned [Signature] 26041 Assistant Foreman
 [Signature] 1479-A Certificate No.
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-17-08 2009 Section or Area Examined Bleeder Const.
 Time of Examination: from 1201 a.m. or PM to 130 a.m. or PM
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>88DK-125 DK20.8%CO2</u>	<u>water in various places</u>	<u>pumping</u>
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1479-A Certificate No. 26041
 Mine Examiner
 Countersigned [Signature] Kyle Anderson Assistant Foreman Certificate No. 33038
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 12-17 Shift 3ve Area or Section Bleeder Coals

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	85 break	2 entry	23 inches	Pumping
2.		3	40+ inches	Pumping
3.				
4.	100 break	4 entry	1 inch	Pumping
5.				
6.	123 Break	1	11 inches	Pumping
7.		2	20 inches	working on it
8.		3	33 inches	Pumping
9.		4	40+ inches	Pumping
10.				

Examinations for Methane in Working Places

1.	Location	Time	Methane Content	Location	Time	Methane Content
1.	Reopened	1 entry	at 123 break	obcft		
2.						
3.	Added discharge line		at one entry			
4.						
5.	Fixed leak in lines					
6.						
7.	and put discharge line		back on one of the pumps			
8.						
9.						
10.						

Examinations for Methane in Return Aircourses

1.	Location	Time	Methane Content	6.	Location	Time	Methane Content
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Ryle Anderson 33238 Etter 26044
 Assistant Mine Foreman Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-17 2004 Section or Area Examined Bleeder
 Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time 10:25 P.M.
 Report received by [Signature]
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>88 BIC 125 BIC ^{WCH4} 20.402 %CO</u>	<u>Water in various places</u>	<u>Pumping</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238 _____ [Signature] 1941A
 President Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned [Signature] 26041 _____
 Mine Manager Mine Foreman

 Assistant Foreman

 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18-20 Section or Area Examined BLEEDER
Time of Examination: from 3 a.m. or p.m. to 5:45 a.m. or p.m.
Was this report phoned to outside? Yes no
By whom KENNETH FARMER Time A.M. 5:45 P.M.
Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Violation or Hazardous Condition, Action Taken. Rows include entries like '68BK 4 ENTRY 00.5 CH4 OX 20.8 WATER 48' #', '88BK 3 ENTRY 00.5 CH4 OX 20.8 WATER 24'', '100BK 1 ENTRY 00.5 CH4 OX 20.8 NOWATER', etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. The table is mostly empty with some faint lines.

Remarks: I always clear water in several different places pumps are running and setting and pumps 00.5 ch4 found OX 20.8

Set 10 sand jacks in old #2 return 83 Bak 7 87 Bak

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 32284 Assistant Foreman [Signature] Certificate No. 36025
Countersigned [Signature] Mine Manager Mine Foreman [Signature] Certificate No. 26041 Assistant Foreman [Signature] Certificate No. 1479A
Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18 209 Section or Area Examined Bleeder Sectors
 Time of Examination: from 1200 a.m. or p.m. to 130 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Kyle Tuberson (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 break to 126 break</u>	<u>Water in various places</u>	<u>pumping</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 26 off + water in several places and pumping
20-8

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1479-A
 Countersigned _____ Mine Manager Mine Foreman Assistant Foreman
[Signature] Assistant Foreman Certificate No. 33238
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18 207 Section or Area Examined Bladder Sect
 Time of Examination: from 900 a.m. or p.m. to 1030 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time A.M. P.M.
 Report received by Ryk Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85 Break to 126	water in various places	Pumping
2. <u> </u>	<u> </u>	<u> </u>
3. 85 Break 3 entry	23 inches	Pumping
4. <u> </u> 4	48 inches	Pumping
5. 100 Break	check	Remaining
6. <u> </u>	<u> </u>	<u> </u>
7. 123 3 entry	31 inches	Pumping
8. <u> </u> 4 entry	48 inches	Pumping
9. <u> </u>	<u> </u>	<u> </u>
10. 126 2 entry	20 inches	Pumping

Air Measurements

Location	CFM	Location	CFM

Remarks: 0704 208
Travelled from 85 to 126 break

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Ryk Anderson Certificate No. 37038
 Preshift-Mine Examiner Assistant Foreman Certificate No.
 Countersigned Mine Manager Mine Foreman Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-21 207 Section or Area Examined _____
 Time of Examination: from 1200 a.m. or p.m. to 110 a.m. or p.m.
 Was this report phoned to outside: Yes No
 By whom Jay Bud Bloughout Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>74BK-125BK</u>	<u>water in various places</u>	
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: OCH4 20.8% O2 0% CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1479-A [Signature] 33238
 Certificate No. _____
 Countersigned [Signature] 26041 _____
 Mine Manager Mine Foreman Assistant Foreman

 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-21 209 Section or Area Examined Bladder Sect
 Time of Examination from 9:00 a.m. or p.m. to 10:30 a.m. or p.m.
 Was this report placed to outside? Yes No
 By whom Brought out Time 12:00 A.M. P.M.
 Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	85 to 126	water in various places	pumping
2.			
3.	85 Break 2 entry	31 inches	pumping
4.	3 entry	40+ inches	
5.			
6.	100 1	31 inches	pumping
7.	2	40+ inches	pumping
8.	3	40+ inches	pumping
9.	4	40+ inches	pumping
10.	123 3 entry 4 entry	50 inches 40+ Air Measurements	pumping pumping

Location	CFM	Location	CFM
good air movement			

Remarks: obc 11 208

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned _____
 Mine Manager Mine Foreman Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-22-09 20 09 Section or Area Examined Bleeder Const.
 Time of Examination: from 4 a.m. or p.m. to 5 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kenny Farmer Time 5.32 A.M. P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>74DK-125 DK</u>	<u>water in various places pumping</u>	
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Och4 20.8% O2 0% C10

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 32294 Certificate No.
 Countersigned [Signature] 26041 Assistant Foreman Certificate No. 1978A
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-22 209 Section or Area Examined Bleeker Cond.
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom Jay Bird Time _____ A.M. _____ P.M.
 Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-to 126</u>	<u>water in various places</u>	<u>Pumping</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	_____	_____	_____
<u>0% CH4</u>	_____	_____	_____
<u>2.8% O2</u>	_____	_____	_____
<u>0% CO</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1479-A Certificate No. Kyle Anderson Assistant Foreman 33298 Certificate No.
 Countersigned [Signature] Mine Manager Mine Foreman [Signature] Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-22- 2009 Section or Area Examined Bleeder
 Time of Examination: from 10:00 a.m. or 11:00 a.m. or 11:00 p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time 11:15 A.M. P.M.
 Report received by Shanklin (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-126</u>	<u>Water in various places</u>	<u>pumply water</u>
2. _____	_____	_____
3. <u>85-Break 2</u>	<u>24 inches</u>	_____
4. _____ 3	<u>40T inches</u>	_____
5. <u>100 Break 1</u>	<u>20 inches</u>	<u>All have pumps</u>
6. _____ 2	<u>31 inches</u>	
7. _____ 3	<u>40T inches</u>	
8. _____ 4	<u>40T inches</u>	
9. _____	_____	_____
10. <u>123 3</u>	<u>31 inches</u>	_____
_____ 4	<u>40T inches</u> Air Measurements	_____

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 20.8 O2 0% CH4 0% CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238 Certificate No. _____ Assistant Foreman
 Countersigned Stager 26041 Certificate No. _____
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-23-2009 Section or Area Examined 2 section
 Time of Examination from 10:10 a.m. or p.m. to 11:20 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Gregory May Time 11:25 A.M. P.M.
 Report received by James Ferguson (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1	None observed	
2	None observed	
3	None observed	
4	None observed	
5	3L	
6	4	
7		
8		
9		
10		

Air Measurements

Location	CFM	Location	CFM

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____
 Preshift-Mine Examiner
 Certificate No. _____ Assistant Foreman
 Countersigned _____
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-23 2009 Section or Area Examined Bleeder Cows
 Time of Examination: from 100 a.m. or p.m. to 230 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom [Signature] Time 235 A.M. P.M.
 Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>856/26 Break</u>	<u>Water in various places</u>	
2. _____	_____	_____
3. <u># 1</u>	<u>Clear</u>	_____
4. <u># 2</u>	<u>H</u>	<u>2 pumps running</u>
5. <u># 3</u>	<u>33 inches</u>	<u>2 pumps running</u>
6. <u># 4</u>	<u>dropped 3 1/2 inches 10</u>	<u>Reported</u>
7. _____	<u>3 pumps running</u>	_____
8. _____	<u>2 in water not draining</u>	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% H₂ 20.8

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1479-A [Signature] 33038
 Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned [Signature] 26041 _____
 Mine Manager Mine Foreman Assistant Foreman

 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____	Certificate No. _____	Mine Foreman-Mine Manager _____	Certificate No. _____	Superintendent or Assistant _____
------------------------------	-----------------------	---------------------------------	-----------------------	-----------------------------------

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-23 209 Section or Area Examined Blender Section
 Time of Examination: from 900 a.m. or p.m. to 1000 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time A.M. P.M.
 Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	85-t 126	Water various places	pumping
2.			
3.	85 Break 2	24 inches	pumping all
4.	3	40 7 inches	
5.	100 Break 1	none	
6.	2	30T	
7.	3	40T	
8.	4	40T	
9.	126 3	33 inches	
10.	4	40T	

Air Measurements

Location	CFM	Location	CFM
good air movement			

Remarks: 2 fact f 20.8 02 CO^e

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238 Certificate No.
 Countersigned Chagan 26001
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-09 20:09 Section or Area Examined Bledner Const.
Time of Examination: from 4:00 a.m. or p.m. to 5:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom K. FARMER Time 5:35 A.M. P.M.
Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for 85-125 Blk, 85 Break, 100 Break, 126 Break, 125 Blk, 124 Blk.

Good Air movement

Remarks: OCH4 20.8% O2 0% CO.
Trunkways clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 32294
Countersigned [Signature] Certificate No. 26041
Assistant Foreman [Signature] Certificate No. 1479-A
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-2009 Section or Area Examined Bleeder Coals
 Time of Examination: from 1:00 a.m. or p.m. to 2:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>886 / 26 Break</u>	<u>Water in various places</u>	<u>Pumping</u>
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: 0.05% CH4 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By: [Signature] 1479-A Certificate No. 26041
 Preshift-Mine Examiner
 Countersigned: [Signature] Assistant Foreman
 Mine Manager Mine Foreman
 Assistant Foreman

 Superintendent or Assistant

33238
Certificate No.

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-09 2009 Section or Area Examined Bleeder Const.
 Time of Examination: from 9:00 a.m. or p.m. to 10:41 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time 11:10 P.M.
 Report received by [Signature] 1947-A
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>65-126 BRK</u>	<u>Water IN various Places</u>	<u>Pumping water</u>
2.	<u>85 Break 2 entry</u>	<u>36 inches</u>	<u>all are pumping</u>
3.	<u>3 entry</u>	<u>40 inches</u>	
4.	<u>100 Break 2 entry</u>	<u>31 inches</u>	
5.	<u>3 entry</u>	<u>36 inches</u>	
6.	<u>4 entry</u>	<u>36 inches</u>	
7.	<u>123 Break 3 entry</u>	<u>36 inches</u>	
8.	<u>4 entry</u>	<u>40 inches</u>	
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: 0% CH₄, 20.8% O₂, 0 PPM CO₂ Detected At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson Certificate No. 33238
 Preshift Mine Examiner
 Countersigned [Signature] Certificate No. 26041
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 12-27 209 Section or Area Examined Bleeders Cons.
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom Jay Bud Time _____ A.M. _____ P.M.
 Report received by [Signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>85 to 126</u>	<u>water in various places</u>	<u>pumping</u>
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			

Remarks: 20.4 20.8

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1477-A Certificate No.
 Countersigned [Signature] 26041 Assistant Foreman 33238 Certificate No.
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-27 20 9 Section or Area Examined Bleeder Cons
Time of Examination: from 9:00 a.m. or p.m. to 10:30 a.m. or p.m.
Was this report placed to outside: Yes no
By whom Brought Out Time A.M./2:00 P.M.
Report received by Kyle Anderson (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Includes entries for locations 85-126, 85, 100, and 125 with details on water levels and pumping actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'good air movement'.

Remarks: 26 O2 20.8 06 CO2

pumps at 85 break seem not to have enough air getting to them. Elects have been notified and are going to check out air Com.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson (MINE EXAMINER)
Countersigned [Signature] (MINE FOREMAN)
Certificate No. 26041
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-28-09 20 08 Section or Area Examined Bleeder const.
 Time of Examination: from 4:00 a.m. or p.m. to 5:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kenny Farmer Time 5:50 A.M. P.M.
 Report received by Jensen Thomas (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>85BK-126BK</u>	<u>water in various places</u>	<u>pumping</u>
2.	<u>25BK #2 entry</u>	<u>30 inches water</u>	<u>11 11</u>
3.	<u>#3 entry</u>	<u>40 inches water</u>	<u>11 11</u>
4.	<u>100 Break #2</u>	<u>none</u>	<u>12 11</u>
5.	<u>#3</u>	<u>20 inches water</u>	<u>11 11</u>
6.	<u>#4</u>	<u>31 inches water</u>	<u>11 11</u>
7.	<u>123 BK #3 entry</u>	<u>15 inches water</u>	<u>11 11</u>
8.	<u>#4 entry</u>	<u>26 inches water</u>	<u>11 11</u>
9.	<u>125 Bnk #1 entry</u>	<u>0</u>	
10.	<u>#2 entry</u>	<u>0</u>	

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: 0.03% CH4 20.8% O2
Tracks & haulways clean at time of exam
still low on #85 Bnk

Replaced one pump at 124 Bnk #3 entry
Repaired discharge on pump at 100 Bnk #3 entry
Repaired section on pump at 122 Bnk #4 entry

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 30294
 Countersigned [Signature] Mine Manager Mine Foreman Assistant Foreman
 Assistant Foreman [Signature] Assistant Foreman
 Superintendent or Assistant [Signature] Superintendent or Assistant
 Certificate No. 1479-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-28- 2009 Section or Area Examined Bleeder const
 Time of Examination: from 1205 a.m. or 130 p.m. to 130 a.m. or 130 p.m.
 Was this report phoned to outside: Yes No
 By whom Brought out Time 245 A.M. P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>85BK - 126BK</u>	<u>water in various places</u>	<u>pumping</u>
2.	<u>85BK #2entry</u>	<u>27 inches water</u>	↓
3.	<u>#3entry</u>	<u>410 inches water</u>	
4.	<u>100BK #2entry</u>	<u>10 inches water</u>	
5.	<u>#3entry</u>	<u>21 inches water</u>	
6.	<u>#4entry</u>	<u>40 inches water</u>	
7.	<u>123 DK #3entry</u>	<u>13 inches water</u>	
8.	<u>#4entry</u>	<u>24 inches water</u>	
9.	<u>125BK #1entry</u>	<u>none observed</u>	
10.	<u>#2entry</u>	<u>none observed</u>	

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: 0.02% CH4 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 147A-A
 Preshift-Mine Examiner Assistant Foreman
 Countersigned [Signature] Certificate No. 33359
 Mine Manager Mine Foreman Assistant Foreman
 Assistant Foreman Superintendent or Assistant

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____	Certificate No. _____	Mine Foreman-Mine Manager _____	Certificate No. _____	Superintendent or Assistant _____
------------------------------	-----------------------	---------------------------------	-----------------------	-----------------------------------

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-28 2009 Section or Area Examined Bleeder
 Time of Examination: from 9:00 a.m. or 6:00 p.m. to 10:30 a.m. or 6:00 p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time _____ A.M. _____ P.M.
 Report received by Shubert (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85BK - 125BK	Water various places	Pumps ↓
2. 85BK #2 entry	27 inches water	
3. #3 entry	10 inches water	
4. 100BK #2 entry	10 inches water	
5. #3 entry	21 water	
6. #4 entry	40 inches water	
7. 123BK #3 entry	13 inches water	
8. #4 entry	24 inches water	
9. 125BK #1 entry	none observed	
10. #2 entry	none observed	

Air Measurements

Location	CFM	Location	CFM
Good agreement			

Remarks: 20.802 0% CH4 0% CO2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33038 Certificate No. _____ Assistant Foreman
 Countersigned Tyler Moore 33389 Certificate No. _____ Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-29 20 09 Section or Area Examined Bleeder const.
Time of Examination: from 1201 a.m. or p.m. to 100 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations like 85DK-125BK, 85DK #3 entry, 100BK #1, etc., and actions like pumping, clear, pumps.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air movement'.

Remarks: 0.0190 CH4 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner
Countersigned [Signature] Mine Manager - Mine Foreman
Certificate No. 33389
Assistant Foreman [Signature] Kyle Anderson
Certificate No. 33238
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported.

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-29 2009 Section or Area Examined Bleeder
 Time of Examination: from 9:00 a.m. or p.m. to 1:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Kyle Anderson Time 1:00 P.M.
 Report received by Shad Wahn (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85B1C 125B1C	Water in various places	pumping
2. 85B1C #3 entry	2 pumps	↓
3. #2 entry	5 pumps	
4.		
5. 100B1C #1 entry	clear	
6. #2 entry	clear	
7. #3 entry	3 3" pumps	
8. #4 entry	4 3" pumps	
9. 123B1C #4 entry	3 pumps	
10. #3 entry	1 pump	

Air Measurements

Location	CFM	Location	CFM
good Air movement			

Remarks: 0.0 % CH4 0% O2 20.8 O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson 33238 Certificate No.
 Countersigned Tony Moore 33359 Certificate No.
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-30-04 20 Section or Area Examined Bleeder
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom H. Farmer Time 5:20 AM P.M.
 Report received by St. J. Young (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85 - 125 Ble	Water in Various Places	Pumping
2. 85 Ble #3 entry	5 Pumps Pumping	
3. 100 Ble #1 entry	water down	
4. #2 "	water down	
5. #3 "	water almost down	3 Pumps Pumping
6. #4 "	water way down	4 Pumps Pumping
7. 123 Ble #4 entry	2 Pumps Pumping	
8. #3 "	2 Pumps Pumping	
9. #2 "	water down	
10. 126 Ble #1 "	water down	
126 Ble #4 entry	2 Pumps Pumping	

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0.5 CH₄ appx 20.8% O₂ detected at time of exam

Track of roadways clean at time of exam
added another pump on #3 entry at 123 Ble.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37284 Certificate No.
 Countersigned [Signature] 33359 Certificate No. 1787-D
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Use Indelible Pencil or Ink

Date of Examination 12-30 20 09 Section or Area Examined Bleeder
 Time of Examination: from 12:30 a.m. or p.m. to 3:00 a.m. or p.m.
 Was this report phoned to outside: Yes No
 By whom Brought Over Time _____ A.M. _____ P.M.
 Report received by Jeremy B. Bishoff (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk - 125 brk</u>	<u>Ch⁴ 0.09% Water in Various Places</u>	<u>Pumping</u>
2. <u>85 brk #3 entry</u>	<u>26" at Point of measure</u>	<u>Pumping</u>
3. <u>100 brk #1 + #2</u>	<u>Water Down</u>	<u>Pumps off</u>
4. <u>#3 entry</u>	<u>Water almost Down</u>	<u>Pumping</u>
5. <u>#4 entry</u>	<u>Water almost Down</u>	<u>" "</u>
6. <u>116</u>	<u>Water Down</u>	<u>Pump off</u>
7. <u>123 brk 1x2 entry</u>	<u>Water Down</u>	<u>Pump off</u>
8. <u>#4x3</u>	<u>#4 30" on Left Pump 24" on Right Pump</u>	<u>Pumping</u>
9. <u>#3</u>	<u>9"</u>	<u>Pumping</u>
10. <u>126</u>	<u>Water Down</u>	<u>Pump off</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: Ch⁴ 0.09% CO 0.9% O₂ 20.8% at time of exam

Track travelways clear at time of exam.
Little to no water on #1 + #2 entry on Prop line

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jeremy B. Bishoff 1759-A Certificate No. 33389
 Countersigned Ray Moore Mine Manager Mine Foreman
Kyle Anderson Assistant Foreman Certificate No. 33238
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-30 209 Section or Area Examined Bleeder
 Time of Examination: from 900 a.m. or p.m. to 1030 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time 1200 P.M.
 Report received by Kyle Johnson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	<u>88-126</u>	<u>Water in various places</u>	<u>pumping</u>
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			

Remarks: 26.4% 20.8 O₂ CO₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Johnson 33238 Certificate No. Assistant Foreman Certificate No.
 Countersigned Tony Moore 33357 Mine Manager Mine Foreman
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-31-01 20 Section or Area Examined Bleeder Coast.
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom L. Farmer Time A.M. P.M.
 Report received by St. Jan 21011 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CHY	Violation or Hazardous Condition	Action Taken
1. 85 125 Bk	OK	Water in Place	Pumping
2. 88 Bk #3 entry		water approx 30" 5 Pumps	Pumps
3. +4 "		water approx 48"	
4. 100 Bk #1 entry		water down	
5. +2 "		water down	
6. +3 "		Almost down 3 Pumps	Pumps
7. +4 "		water way down approx 24" - 4 Pumps	Pumps
8. 123 Bk #3 entry		water holding at approx 36" - 2 Pumps	Pumps
9. +4 "		" " " " - 2 Pumps	Pumps
10. +2		water down	
126 Bk #1 entry		Basically down - 1 Pump	Pumps
		2 Pumps	Pumps

Air Measurements

Location	CFM	Location	CFM
Coal Air Movement			

Remarks: OK CHY open co 20-6502

Track & haulways clean at time of exam

Added Pump in #1 entry at approx 98 Bk to Pump
Small Hole of water down - needs old air hose

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 32294
 Preshift-Mine Examiner
 Countersigned [Signature] Certificate No. 1759-D
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 12-31 20 09 Section or Area Examined Bleeder Construction
 Time of Examination: from 12 ~~00~~ ⁰⁰ P.M. to 3:00 a.m. or P.M.
 Was this report phoned to outside: Yes no
 By whom J. Burdough Time _____ A.M. _____ P.M.
 Report received by W. L. [Signature] 1354A
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brd</u>	<u>24" at Point of Measure</u>	<u>Pumpins</u>
2. <u>100 brd 1A2 entry</u>	<u>Pump Off no water</u>	<u>none</u>
3. <u>4 entry</u>	<u>21" at Point of Measure</u>	<u>Pumpins</u>
4. <u>123 brd 1A2 entry</u>	<u>Water Down</u>	<u>none</u>
5. <u>3 entry</u>	<u>6" at Point of Measure</u>	<u>Pumpins</u>
6. <u>4 entry</u>	<u>L Pump 30" Rt Pump 28"</u>	<u>Pumpins</u>
7. <u>126 brd 1 entry</u>	<u>39" at Point of Measure</u>	<u>Pumpins</u>
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O₂ 20.4, O₂ 20.0, 20.8% O₂ detected
TRACK/TRAVELWAYS CLEAR at Exam

Add Pump in #1 still needs Air Hose to pump water in #1 entry at 98 brd 5 in water

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 189A Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager Mine Foreman _____ Assistant Foreman _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/11 2004 Section or Area Examined Bleeder
 Time of Examination: from 7:00 a.m. or p.m. to 8:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by Jeremy Buchtut
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-131 brk Ch⁴0.0%</u>	<u>Water in Various Places</u>	<u>Pumpins</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Ch⁴0.0% CO 0% O₂ 20.8% at time of exam
Tracks, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1758-12
 Countersigned [Signature] Mine Manager Mine Foreman Certificate No. 33359
[Signature] Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-2
 Time of Examination: from 210 a.m. or p.m. to 905 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom T. Moore Time 1069 P.M.
 Report received by Kyle Anderson (Signed)

¹⁸ Section or Area Examined Bleeder Cons

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-126</u>	<u>Water Various places</u>	<u>Pumping</u>
2. <u>85-7 entry</u>	<u>28 inches</u>	
3. <u>4 entry</u>	<u>30+ inches</u>	
4.		
5. <u>100 Break 4</u>	<u>4 pumps pumpen</u>	<u>Pumping</u>
6.		
7.		
8. <u>126 Break 3 entry</u>	<u>24 inches</u>	
9. <u>4 entry</u>	<u>36 inches</u>	
10.		

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			

Remarks: 0.26 CH₄ 20.8 0.20 CO₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson Preshift-Mine Examiner Certificate No. 33238
 Countersigned Troy Moore Mine Manager Mine Foreman Certificate No. 33389
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported.

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-3 2010 Section or Area Examined Bleeder Cons.
 Time of Examination: from 730 a.m. or p.m. to 905 a.m. or p.m.
 Was this report phoned to outside: Yes no Time 11:30 P.M.
 By whom _____
 Report received by Brough out (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	85-126 Break	water various places	Pumping
2.			
3.	85 Break 3	24 inches	pumping
4.	4	32	pumping
5.	100 1 and 2 entry	none	
6.	3	24 inches	pumping
7.	4	30 inches	pumping
8.	125 1 and 2 entry	dry	
9.	3 entry	24 inches	pumping
10.	4	36 inches	Pumping

Air Measurements

Location	CFM	Location	CFM

Remarks: 26 cft 4 20.8 no CO2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Kyle Anderson
 Preshift Mine Examiner
 Countersigned Fry
 Mine Manager / Mine Foreman
 Assistant Foreman

33238
 Certificate No.
39957

Assistant Foreman _____ Certificate No. _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-4 2010 Section or Area Examined Bleeder
 Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (m)
 Was this report phoned to outside: no
 By whom Brought Out Time _____ A.M. _____ P.M.
 Report received by Jeremy Burghoff (signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	85-88 brk	CH ₄ 0.0%	pumpins
2.	98 brk	2 1/2" water at Point of measure	none
3.	100 #4	16" at new Point of Measure	pumpins
4.	#1, 2, 3	Water Down	none
5.	123 #1, 2	Water Down	none
6.	#3	7" water at Point of Measure	Pumping
7.	#4	(Pump 30" 2 pump 27" at Point of Measure	Pumping
8.	118 brk #4	24" at Point of Measure	Pumping
9.	125 brk #4	38" at Point of Measure	Pumping
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: CH₄ 0.0% CO 0% O₂ 20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jeremy Burghoff Preshift-Mine Examiner Certificate No. 1159-A Assistant Foreman Certificate No. _____
 Countersigned Jeremy Burghoff Mine Foreman Certificate No. 33357
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Report shall be signed when made

PRESHIFT-MINE EXAMINER'S REPORT

Use Indelible Pencil or Ink

Date of Examination 115 Section or Area Examined Bleeder
 Time of Examination: from 7:00 (a.m. or p.m.) to 9:00 (a.m. or p.m.)
 Was this report phoned to outside: Yes no Time A.M. P.M.
 By whom Brought out
 Report received by Jeremy Burghoff (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-131 brk</u>	<u>ch⁴ 0.0% water in various places</u>	<u>Pumping</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: ch⁴ 0.0% CO 0.0% O₂ 20.8% at time of exam.
Trect travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jeremy Burghoff 1759-A Certificate No.
 Preshift-Mine Examiner Assistant Foreman
 Countersigned Tony Moore 53359 Certificate No.
 Mine Manager Mine Foreman
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/5 2003 Section or Area Examined Bleeder
 Time of Examination: from 12:00 a.m. or 12:00 p.m. to 3:00 a.m. or 3:00 p.m.
 Was this report phoned to outside: Yes no
 By whom Brought Out Time _____ A.M. _____ P.M.
 Report received by Jeremy Burshoff (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brk</u>	<u>CH⁴ 0.09024" at point of Measure</u>	<u>pumping</u>
2. <u>100 #1*2</u>	<u>Water down</u>	<u>wave</u>
3. <u>#3</u>	<u>7" at point of Measure</u>	<u>pumping</u>
4. <u>#4</u>	<u>28" of water at point of Measure</u>	<u>pumping</u>
5. <u>118</u>	<u>24" at point of Measure</u>	<u>pumping</u>
6. <u>122 #1*#2</u>	<u>Water Down</u>	<u>none</u>
7. <u>#3</u>	<u>CH⁴ 0.059 4" at point of Measure</u>	<u>pumping</u>
8. <u>#4</u>	<u>CH⁴ 0.090 L Pump 28" R pump 25"</u>	<u>pumping</u>
9. <u>125 brk</u>	<u>37" of water at point of measure</u>	<u>pumping</u>
10.		

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: CH⁴ 0.090 CO 0.90 O₂ 20.8% at time of exam.
Track travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759-A Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Foreman _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman _____	Certificate No. _____	Mine Foreman-Mine Manager _____	Certificate No. _____	Superintendent or Assistant _____
------------------------------	-----------------------	---------------------------------	-----------------------	-----------------------------------

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1/16 2010 Section or Area Examined Bleeder
 Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time A.M. P.M.
 Report received by Jeremy Byrd/H (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
<u>85-131 bit</u>	<u>CH₄ 0.0%</u> <u>Water in Various Places</u>	<u>Pumping</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Dir movement</u>			

Remarks: CH₄ 0.0% CO 0% O₂ 20.8% at time of exam.
Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759-A
 Countersigned [Signature] Mine Manager Mine Foreman Certificate No. 33354
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/16 2010 Section or Area Examined Bleeder
 Time of Examination: from 2:00 a.m. or P.M. to 3:00 a.m. or P.M.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 br #1 & #2</u>	<u>CH₄ 0.0%</u> <u>25" of water at Point of Measure</u>	<u>Pumpings</u>
2. <u>101 #1 & #2</u>	<u>Water down</u>	<u>None</u>
3. <u>#3</u>	<u>Water down</u>	<u>None</u>
4. <u>#4</u>	<u>28" at Point of Measure</u>	<u>Pumpings</u>
5. <u>118 br #1 & #2</u>	<u>24" at Point of Measure</u>	<u>Pumpings</u>
6. <u>122 br #1 & #2</u>	<u>Water down</u>	<u>None</u>
7. <u>#3</u>	<u>4" at Point of Measure</u>	<u>Pumpings</u>
8. <u>#4</u>	<u>L Pump 30" R Pump 26 1/2 of water</u>	<u>Pumpings</u>
9. <u>125 br #4</u>	<u>36" at Point of Measure</u>	<u>Pumpings</u>
10. <u>131 br #2 entry at</u>	<u>5" of water</u>	<u>Pumpings</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: CH₄ 0.0% CO 0.9% O₂ 20.8% at time of exam
Treat trackways clear at time of exam
Phones Not Working

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1755-A Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager Mine Foreman 33359
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 117 Section or Area Examined Bleeder
 Time of Examination: from 7:30 a.m. or p.m. to 9:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time A.M. P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken	
1.	<u>85-131 brd</u>	<u>CH₄ 0.0%</u>	<u>Water in various places</u>	<u>Pumping</u>
2.				
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>			

Remarks: CH₄ 0.0% CO₂ 0% O₂ 20.8% at time of exam
Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1755-17
 Countersigned T. Moore Mine Manager Mine Foreman Certificate No. 33359
 Assistant Foreman
 Superintendent or Assistant [Signature] Certificate No. 1759-A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 117 2010 Section or Area Examined Bleeder
 Time of Examination: from 12:00 a.m. or 9 p.m. to 3:00 a.m. or 9 p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time A.M. P.M.
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	85-88 brk	CH ₄ 0.09 2 1/2" of water at point of measure	Pumping
2.	100 brk #1 #2 #3	water Down	none
3.	#4	28" of water at point of measure	Pumping
4.	118 brk #4	23" of water at point of measure	Pumping
5.	122 brk #1 #2	Water Down	None
6.	#3	5" of water at point of measure	Pumping
7.	#4	R pump 27" L pump 30"	Pumping
8.	125 brk #4	36" of water at point of measure	Pumping
9.	131 brk #1	4" of water at point of measure	Pumping
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: CH₄ 0.09 CO 0.8 O₂ 20.8% at time of exam.
Track clear at time of exam
Travelway needs a sand track set at 84"

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1159-A Assistant Foreman Certificate No.
 Countersigned T. [Signature] Mine Manager Mine Foreman 33389
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant