MSHA Form 7000-10H, June 93 (revised)

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4111138

Company Name Performance Coal Co, Inc.

Mine Name Upper Big Branch South

Mine I.D. Number 46-08436

Date(s) of Mine File Review 7/7/00

D Status V Citation/Order No. 7254895 Date 6/3/06

Dates of Inspection: began 8/23 completed 8/23

Pre-Inspection Conference Date 8/23

Company Representative(s)

[redacted]

Miners Representative(s)

None

Post-Inspection Conference Date 8/23

Company Representative(s)

[redacted]

Miners Representative(s)

None

Comments:

Inspector's Initials [redacted] Supervisor's Initials and Date MHH 8/25/06

*U.S. Government Printing Office: 1995 — 609-287

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET I03-I

Date 8-23-06 Event No. 4111138

Arrived at the Mine ——— Departed from the Mine ———

List Records Books Checked

Pre-Shift

Accompanied By: Company Representative

[redacted]

Miners Representative

None.

AREAS OF INSPECTION ACTIVITY:

LOB - 009-0

Section

59,570 CFM

CH4 Readings

NO1	0%	NO4	.1%
NO2	.1%	NO.5	.1%
NO.3	.1%	NO.6	.2%

(Battle Length # N1920)

Inspector's Initials [redacted]

Supervisor's Initials and Date _____ Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 8-23-06 4111138

Battle # N 1920

Tubes in No. 6 entry at Colter, behind the end of the line Curtains.

.2% CH4 detected

Section is very wet!

Inspector's Initials [redacted]

Supervisor's Initials and Date _____ Page No. 2

*U.S.GPO: 2004 - 642 - 912