

RA
4-7-08

U. S. Department of Labor
Mine Safety and Health Administration

Mine Activity Data

1. Action: a. New Entry b. Update 2. Activity Code: E02 3. Event Number: 4120377

4. Date Event Started: 4/3/2008 5. Date Event Finished: 4/3/2008 6. Mine ID: 46-08436

7a. Organization Code (Mine Assignment) 20401 b. Work Group Identifier 02 9. Company Name PERFORMANCE COAL COMPANY

8a. Organization Code (AR Assignment) 20401 b. Work Group 02 10. Mine Name UPPER BIG BRANCH MINE-SOUTH

11. Report Type (check) a. First b. Interim c. Last d. Not Applicable 12. Area of Inspections a. Active Sections 2 b. Idle Sections

c. Outby Areas d. Shafts/Slopes e. Surface Areas (UG) f. Surface Workings g. Company Records h. ATF i. Impoundments j. Refuse Piles

k. Major Construction (1) Shaft/Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/Shovel (5) Other 1. Miscellaneous

m. MMU/Pit Number (1) 029 (2) 030 (3) 040 (4) 041

13. Number of Samples Collected a. Air Samples 4 b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles: a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

a. This Inspection	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
(1) New Issuances	0	0	0	0	0	0	0	0
(2) Terminations/Vacations	0/0	0	0	0	0	0	0	0
(3) Modifications/Extensions	0	0	0	0	0	0	0	0
(4) Left Pending	0	0	0	0	0	0	0	0
b. Previously Issued								
(1) Modifications/Extensions	0/0	0	0	0	0	0	0	0
(2) Terminations/Vacations	2/0	0	0	0	0	0	0	0

18. Signature and Card Number of Authorized Representative/ Right of Entry Person(s) Responsible for Activity

a.  b.  c. _____ d. _____

Card Number 24320

19. Key Entered By _____ Date _____

17. Remarks:

Shift	Sun			Mon			Tue			Wed			Thur			Fri			Sat		
	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
Week 1 3/30/2008	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																		

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration

RR
4-7-08



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 03/19/2008	3. Citation/ Order Number 7279747 - 01
4. Served To Gary May, Mine Foreman	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436 (Contractor)	

Section II--Justification for Action

The areas that were not in compliance, outby the #2 section (MMU 040, 041) has been rock dusted.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 4120377		
11. Signature [Redacted]	AR Number 24320	12. Date Mo Da Yr 04/03/2008	13. Time (24 Hr. Clock) 1500

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration

RR
4.7-08


Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 03/24/2008	3. Citation/ Order Number 7279749 - 02
4. Served To Gary May, Mine Foreman	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

The areas that were not in compliance, outby the #1 section (MMU 029,030) has been rock dusted.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 4120377		
11. Signature 	AR Number 24320	12. Date Mo Da Yr 04/03/2008	13. Time (24 Hr. Clock) 1505

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) 03/19/2008 Mo Da Yr	3. Citation/ Order Number 7279747 - 01
4. Served To Gary May, Mine Foreman	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

The areas that were not in compliance, outby the #2 section (MMU 040, 041) has been rock dusted.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 4120377		
11. Signature [Redacted]	AR Number 24320	12. Date Mo Da Yr 04/03/2008	13. Time (24 Hr. Clock) 1500