

RR
 3-12-08

Mine Activity Data

1. Action: a. New Entry b. Update 2. Activity Code: E02 3. Event Number: 4120613

4. Date Event Started: 3/10/2008 5. Date Event Finished: 3/10/2008 6. Mine ID: 46-08436

7a. Organization Code (Mine Assignment) 20401 b. Work Group Identifier 02 9. Company Name PERFORMANCE COAL COMPANY

8a. Organization Code (AR Assignment) 20401 b. Work Group 02 10. Mine Name UPPER BIG BRANCH MINE-SOUTH

11. Report Type (check) a. First b. Interim c. Last d. Not Applicable 12. Area of Inspections a. Active Sections 1 b. Idle Sections 0

c. Outby Areas d. Shafts/Slopes e. Surface Areas (UG) f. Surface Workings g. Company Records h. ATF i. Impoundments j. Refuse Piles

k. Major Construction (1) Shaft/Slope Sinking 0 (2) Impoundment Construction 0 (3) Buildings 0 (4) Dragline/Shovel 0 (5) Other 0 l. Miscellaneous

m. MMU/Pit Number

(1) 040 (2) 041

13. Number of Samples Collected a. Air Samples 3 b. Rock Dust Spot 0 c. Rock Dust Survey 0 d. Respirable Dust 0 e. Noise 0 f. Other 0


14. Impoundments/Refuse Piles:
 a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

a. This Inspection	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
(1) New Issuances	0	0	0	0	0	0	0	0
(2) Terminations/Vacations	1/2	0/0	0/0	0/0	0/0	0/0	0/0	0/0
(3) Modifications/Extensions	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
(4) Left Pending	0	0	0	0	0	0	0	0
b. Previously Issued								
(1) Modifications/Extensions	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
(2) Terminations/Vacations	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0

18. Signature and Card Number of Authorized Representative/
 Right of Entry Person(s) Responsible for Activity

a. 
 b. _____
 c. _____
 d. _____

Card Number
 24329

19. Key Entered By

Date

17. Remarks:

Bottle Samples: Outby seal sets #8 (W0484), #7 (W5047), #6 (W5056). The seals were outgasing. Pumped to check atmosphere behind seals. #8 0 CH4 and 20.8 O2, #7 1.9 CH4 and 12.7 O2, #6 4.9 CH4 and 6.2 O2.

Shift	Sun			Mon			Tue			Wed			Thur			Fri			Sat		
	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
Week 1 3/9/2008	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>															

Previously issued



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue)	Mo Da Yr 03/03/2008	3. Citation/ Order Number	7279736 - 02
4. Served To William Harless; Mine Foreman	5. Operator PERFORMANCE COAL COMPANY			
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436		(Contractor)	

Section II--Justification for Action

Line brattices were provided for the No. 1 and No. 2 faces of the No. 2 Section butt off.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date	Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------	----------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection	E02	10. Event Number	4120613	
11. [Redacted]	AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Clock)
	24329		03/10/2008	1314

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 03/06/2008	3. Citation/ Order Number 7279740 - 01
4. Served To Rick Hodge; Superintendant	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436 (Contractor)	

Section II--Justification for Action

The operator provided evidence that the Stancor pump was permissible.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input checked="" type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------------------	------------------------	--	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection FOI	10. Event Number 4120613	
AR Number 24329	12. Date Mo Da Yr 03/10/2008	13. Time (24 Hr. Clock) 1303

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) 03/06/2008	3. Citation/ Order Number 7279741 - 01
4. Served To Rick Hodge; Superintendant	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

The operator provided evidence that the Flygt pump was permissible.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input checked="" type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------------------	------------------------	--	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 4120613		
11. [Redacted]	AR Number 24329	12. Date Mo Da Yr 03/10/2008	13. Time (24 Hr. Clock) 1310