

Preliminary Report of Accident



| | | | | |
|-----------------------------------|---|---|--|-----------------------|
| 1. Accident Type: Fatal Injury | 2. Accident Classification Machinery | 3. Date/Time of Accident 02/13/2013 08:30 PM | 4. Date/Time of Death 02/13/2013 10:00 PM | 5. Fatal Case No 4 |
|-----------------------------------|---|---|--|-----------------------|

6. Mine Information :

| | | |
|--|--|---|
| a) Mining Company Name Knight Hawk Coal LLC | b) Mine Name Prairie Eagle South Underground Mine | c) Parent of Mining Company Arch Coal Inc.; Franklin D. Robertson; James O. Bunn |
|--|--|---|

| | | | | | |
|--------------------|-------------------|--------------------|----------------|--------------------------------|-----------------|
| 7. Mine Location : | a) City Cutler | b) County Perry | c) State IL | 8. Mine ID Number: 11-03205 | 9. Union: NO |
|--------------------|-------------------|--------------------|----------------|--------------------------------|-----------------|

| | | | | | | |
|---|-------------------------------|----------------|----------------------|--------------------|--------------------|----------|
| 10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND | 11. Number of Mine Employees: | a) Total 51 | b) Underground 51 | c) Open Pit/Quarry | d) Mill/Prep Plant | e) Other |
|---|-------------------------------|----------------|----------------------|--------------------|--------------------|----------|

| | | |
|----------------------|-----------|---------------------------|
| 12. Contractor Name: | 13. Union | 14. Contractor ID Number: |
|----------------------|-----------|---------------------------|

| | | | | |
|-------------------------|---------|-----------|----------|-------------|
| 15. Contractor Address: | a) City | b) County | c) State | d) Zip Code |
|-------------------------|---------|-----------|----------|-------------|

| | | | | | |
|-------------------------------------|----------|----------------|--------------------|--------------------|----------|
| 16. Number of Contractor Employees: | a) Total | b) Underground | c) Open Pit/Quarry | d) Mill/Prep Plant | e) Other |
|-------------------------------------|----------|----------------|--------------------|--------------------|----------|

| | |
|--|--|
| 17. Number of Persons in Mine at Time of Accident: | 18. Number of Persons Unaccounted For: |
| a) Mine Employees: 16 | b) Contractor Employees: 0 |
| a) Mine Employees: 0 | b) Contractor Employees: 0 |

| | | | | | | |
|--------------------------|--|---|--|---|--|--------------------|
| 19) Location of Accident | <input checked="" type="checkbox"/> 01-Underground | <input type="checkbox"/> 03-Open Pit | <input type="checkbox"/> 07-Advance Mining | <input type="checkbox"/> 30-Mill/Prep Plant | <input type="checkbox"/> Other (specify) | 20. Mining Height: |
| | <input type="checkbox"/> 02-Surface at Underground | <input type="checkbox"/> 06-Dredge Mining | <input type="checkbox"/> 08-Retreat Mining | <input type="checkbox"/> 99-Office Facility | | Feet Inches |
| | | | | | | 7 4 |

| | |
|------------------------|--------------------------|
| 21. Nonfatal Injuries: | 22. Fatal Injuries: 1 |
|------------------------|--------------------------|

| | | |
|--------------------------|--------------------------------|--------------|
| 23. Victim Information : | a) Name Timothy K. Chamness | b) Age 28 |
|--------------------------|--------------------------------|--------------|

| | | |
|--|---|---|
| c) Regular Job Title: Continuous Miner Operator | d) Activity at Time of Accident: Continuous Miner Operator | <input checked="" type="checkbox"/> Mine Employee |
|--|---|---|

| | | | | |
|------------------|------------------|-----------------------|-------------------------|--------------------|
| 24. Experience : | Years Weeks Days | Years Weeks Days | Years Weeks Days | Years Weeks Days |
| a) Total: | 4 7 4 | b) at the mine: 2 6 0 | c) at activity (23d) 26 | d) with Contractor |

| | |
|--|---|
| 25. Autopsy Performed: If Yes, Location YES To Be Announced | 26. Mine Telephone No.: (618) 497-2768 |
|--|---|

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
A continuous miner operator received fatal crushing injuries. The operator was pinned between the tail of the continuous miner and the coal rib while mining coal at the face area of the No. 1 entry of the 3rd North section.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

| | |
|---|---------------------------|
| 28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co) | 29. Model: 14CM15-11EX |
|---|---------------------------|

| | | |
|----------------------------------|--------------------------------|------------------------------|
| 30. District: C0800 Vincennes | 32. Field Office: Benton IL | 33. Event Number: 4254418 |
|----------------------------------|--------------------------------|------------------------------|

| | | | |
|---|---|--------------------|------------------|
| 34. Accident Investigator: Harry E. Wilcox | 35. MSHA Person Notified: Steve Miller | Date 02/13/2013 | Time 09:05 PM |
|---|---|--------------------|------------------|

| | | |
|--------------------------------|---|--------------------|
| 36. Type of Report: Amended | 37. Name of Preparer and Date Prepared: Harry Wilcox | Date 02/13/2013 |
|--------------------------------|---|--------------------|

38. Reason For Amendment:
Correct accident time.