

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 01/16/2014 09:05 PM		4. Date/Time of Death 01/16/2014 09:05 PM		5. Fatal Case No 1						
6. Mine Information :														
a) Mining Company Name Mettiki Coal WV, LLC			b) Mine Name Mountain View Mine			c) Parent of Mining Company Alliance Resource Partners LP								
7. Mine Location :		a) City Davis		b) County Tucker		c) State WV		8. Mine ID Number: 46-09028		9. Union: NO				
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUN			11. Number of Mine Employees:		a) Total 180	b) Underground 156	c) Open Pit/Quarry 0	d) Mill/Prep Plant 24	e) Other 0					
12. Contractor Name:						13. Union		14. Contractor ID Number:						
15. Contractor Address:														
a) City		b) County			c) State			d) Zip Code						
16. Number of Contractor Employees:														
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other						
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:									
a) Mine Employees: 55		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0							
19) Location of Accident								20. Mining Height:						
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> 99-Office Facility	<input type="checkbox"/> Other (specify)	Feet	Inches				
7	0													
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1												
23. Victim Information :														
a) Name Daniel Lambka				b) Age 20										
c) Regular Job Title: General Inside Laborer				d) Activity at Time of Accident: General Inside Laborer				<input checked="" type="checkbox"/> Mine Employee						
24. Experience :														
Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days			
a) Total:	2	24	0	b) at the mine:	17	0	c) at activity (23d)	2	24	0	d) with Contractor	0	0	0
25. Autopsy Performed: If Yes, Location YES Morgantown, WV						26. Mine Telephone No.: (304) 259-4910								

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Thursday, January 16, 2014, at approximately 9:00 PM, a general inside laborer was fatally injured. The victim was standing between the coal rib and the feeder on the F-Main Section. The securing post (jill-poke) became dislodged and allowed the feeder to shift and pin the victim between the rib and the frame of the feeder. The victim had just finished connecting a chain between the feeder and the tail piece when the accident occurred.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co)			29. Model: BF-14-37-74C		
30. District: C0300 Morgantown		32. Field Office: McHenry			33. Event Number:
34. Accident Investigator: Franklin D. Thomas			35. MSHA Person Notified: Gregory W. Fetty [DataTrac]		Date 01/16/2014
Time 09:15 P					
36. Type of Report: Initial		37. Name of Preparer and Date Prepared LS for Bob E. Cornett, DM for MTC			Date 01/17/2014
38. Reason For Amendment:					