

Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Falling, Rolling or Sliding Rock /Materl	3. Date/Time of Accident 08/03/2015 02:45 PM	4. Date/Time of Death 08/03/2015 03:00 PM	5. Fatal Case No
-----------------------------------	--	---	--	------------------

6. Mine Information :

a) Mining Company Name Pinky's Aggregates Inc	b) Mine Name Pinky's Aggregates Inc	c) Parent of Mining Company Dale Honsey
--	--	--

7. Mine Location :	a) City Rolette	b) County Rolette	c) State ND	8. Mine ID Number: 32-00909	9. Union: NO
--------------------	--------------------	----------------------	----------------	--------------------------------	-----------------

10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M	11. Number of Mine Employees:	a) Total 6	b) Underground 0	c) Open Pit/Quarry 6	d) Mill/Prep Plant 0	e) Other 0
--	-------------------------------	---------------	---------------------	-------------------------	-------------------------	---------------

12. Contractor Name:	13. Union	14. Contractor ID Number:
----------------------	-----------	---------------------------

15. Contractor Address:	a) City	b) County	c) State	d) Zip Code
-------------------------	---------	-----------	----------	-------------

16. Number of Contractor Employees:	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
-------------------------------------	----------	----------------	--------------------	--------------------	----------

17. Number of Persons in Mine at Time of Accident:	18. Number of Persons Unaccounted For:
a) Mine Employees: 6	a) Mine Employees: 0
b) Contractor Employees: 0	b) Contractor Employees: 0

19) Location of Accident	20. Mining Height:
<input type="checkbox"/> 01-Underground <input type="checkbox"/> 02-Surface at Underground <input checked="" type="checkbox"/> 03-Open Pit <input type="checkbox"/> 06-Dredge Mining <input type="checkbox"/> 07-Advance Mining <input type="checkbox"/> 08-Retreat Mining <input type="checkbox"/> 30-Mill/Prep Plant <input type="checkbox"/> 99-Office Facility <input type="checkbox"/> Other (specify)	Feet 10 Inches

21. Nonfatal Injuries: 0	22. Fatal Injuries: 1
-----------------------------	--------------------------

23. Victim Information :	a) Name William Makela	b) Age 64
--------------------------	---------------------------	--------------

c) Regular Job Title: Loader Operator	d) Activity at Time of Accident: Loading Trucks	<input checked="" type="checkbox"/> Mine Employee
--	--	---

24. Experience :	Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days
a) Total:	0 44 0	b) at the mine:	0 14 0	c) at activity (23d):
d) with Contractor:	0 0 0			

25. Autopsy Performed: If Yes, Location	26. Mine Telephone No.: (701) 246-3880
--	---

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim had been loading trucks with a Deere 724J Front-End Loader from the stockpile when he exited the vehicle. The face of the stockpile sloughed. The victim was found between the stockpile and the Front-End Loader buried under material from the stockpile.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Deere & Co.	29. Model: 724J
--	--------------------

30. District: M6000 Rocky Mountain	32. Field Office: Rapid City SD	33. Event Number: 6696940
---------------------------------------	------------------------------------	------------------------------

34. Accident Investigator: Leon Mueller	35. MSHA Person Notified: Pete Del Duca	Date 08/03/2015	Time 03:15 PM
--	--	--------------------	------------------

36. Type of Report: Initial	37. Name of Preparer and Date Prepared: Pete Del Duca	Date 08/04/2015
--------------------------------	--	--------------------

38. Reason For Amendment: