

PR001
29-Apr-13

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 04/27/2013 10:20 AM		4. Date/Time of Death 04/27/2013 10:45 AM		5. Fatal Case No 6		
6. Mine Information :										
a) Mining Company Name Allied Custom Gypsum			b) Mine Name ACG #1 Shamrock			c) Parent of Mining Company Charles W Harrison Jr				
7. Mine Location :		a) City Shamrock		b) County Wheeler		c) State TX		8. Mine ID Number: 41-04758		9. Union: NO
10. Primary Mineral Mined: GYPSUM MINING		11. Number of Mine Employees:		a) Total 13	b) Underground	c) Open Pit/Quarry 12	d) Mill/Prep Plant		e) Other 1	
12. Contractor Name:					13. Union		14. Contractor ID Number:			
15. Contractor Address		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees 6		b) Contractor Employees			a) Mine Employees 0		b) Contractor Employees			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries:		22. Fatal Injuries: 1								
23. Victim Information :				a) Name James D. Winegeart		b) Age 58				
c) Regular Job Title: Mechanic/Pit Truck operator			d) Activity at Time of Accident: Cleaning out rock on return roller			<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		YearsWeeksDays		YearsWeeksDays		YearsWeeksDays		YearsWeeksDays		
a) Total:		2 9		b) at the mine: 2 9		c) at activity (23d) 2 9		d) with Contractor		
25. Autopsy Performed: If Yes, Location YES Lubbock, TX						26. Mine Telephone No: (806) 256-1200				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was attempting to clear a blockage on a mobile track-mounted crusher when he became entangled in the discharge conveyor.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Construction Equipment company			29. Model: 102/152W		
30. District: M5000 South Central		32. Field Office: Carlsbad NM		33. Event Number: 6608161	
34. Accident Investigator: Maria Rich		35. MSHA Person Notified: Michael Franklin		Date Time 04/27/2013 10:53 A	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>		Date 04/29/2013	
38. Reason For Amendment:					