

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 06/13/2013 01:34 PM		4. Date/Time of Death 06/13/2013 02:24 PM		5. Fatal Case No 9	
6. Mine Information :									
a) Mining Company Name Stevens Creek Quarry Inc			b) Mine Name Stevens Creek Quarry			c) Parent of Mining Company Richard Voss			
7. Mine Location : a) City Cupertino			b) County Santa Clara		c) State CA		8. Mine ID Number: 04-01676		9. Union: YES
10. Primary Mineral Mined: CRUSHED & BROKEN STONE MININ			11. Number of Mine Employees: a) Total 16		b) Underground 2		c) Open Pit/Quarry		d) Mill/Prep Plant 14
12. Contractor Name:					13. Union		14. Contractor ID Number:		
15. Contractor Address:									
a) City			b) County			c) State		d) Zip Code	
16. Number of Contractor Employees:									
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:				
a) Mine Employees: 16		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees:		
19) Location of Accident								20. Mining Height:	
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)	
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches	
21. Nonfatal Injuries:			22. Fatal Injuries: 1						
23. Victim Information :									
a) Name Jose A. Gonzalez					b) Age 50				
c) Regular Job Title: Mechanic					d) Activity at Time of Accident: Operating haul truck				
<input checked="" type="checkbox"/> Mine Employee									
24. Experience :									
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days
a) Total: 15 15 5			b) at the mine: 15 15 5			c) at activity (23d): 15 15 5			d) with Contractor
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (408) 253-2512			

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating a 35 ton articulated haul truck down a haul road. The truck went out of control and hit a berm, propelling it in the air. The truck came to a stop with the bed overturned and the cab upright. The victim was ejected from the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Volvo			29. Model: A35D		
30. District: M7000 Western		32. Field Office: Vacaville CA			33. Event Number: 6592442
34. Accident Investigator: Chad Hilde			35. MSHA Person Notified: Patricia Borer		Date 06/13/2013
					Time 02:46 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 06/14/2013
38. Reason For Amendment:					